

Ardmore Park Quarry

Annual Review

1 January 2024 - 31 December 2024



Site information

Site Name	Ardmore Park Quarry
Address	5152 Oallen Ford Road, Bungonia NSW, 2580
Project Approval	PA 07_0155 (Mod 3)
Environmental Licence	EPL 13213

Company information

Name	CEAL Limited (Multiquip Quarries)
Registered Address	260 Tenth Avenue, Austral NSW, 2079
Post Address	PO Box 4, Austral, 2079
Australian Business Number	44 101 930 714
Email	enquiries@multiquip.com.au
Phone	02 9606 0557

Document information

Author (Company)	Date	Changes	Reviewer (Company)	ID
Rhys Thompson (4Pillars Environmental Consulting)	21/03/2025	N/A	Stephen Wall (Multiquip Aggregates)	Draft V0.1
Rhys Thompson (4Pillars Environmental Consulting)	26/03/2025	Finalising unfinished sections, addressing comments, updating noncompliances, revising legislation references.	Stephen Wall (Multiquip Aggregates)	Draft V0.2
Rhys Thompson (4Pillars Environmental Consulting)	3/04/2025	Including production data and minor operational updates.	Stephen Wall (Multiquip Aggregates)	Final Draft V1.0
Rhys Thompson (4Pillars Environmental Consulting)	7/04/2025	Minor revisions, referring to non-compliance notification.	Stephen Wall (Multiquip Aggregates)	Final V1.1

Contents

I. Title	· block	6
II. Stat	tement of compliance	7
1. Intro	oduction	8
1.1	Project description	8
1.2	AR overview	10
1.3	Key personnel	10
2. Арр	provals	11
2.1 E	Existing approvals	11
2.2 N	Modifications and amendments	12
3. O pe	erations summary	12
3.1 C	Quarrying	12
3.2 C	Compliance and returns	13
3.3 R	Roadworks	13
3.4 T	Fruck movements	14
3.5 C	Compliance with transport limits	14
lm	provements to weighbridge management	15
20)23 Annual Review	15
4. Acti	ivities proposed in the previous AR	16
5. Envi	ironmental performance	18
5.1 N	Monitoring points	18
5.2 N	Meteorological data	18
5.3 A	Air quality	20
De	eposited Dust	21
Pa	articulate matter	22
5.3	3.1 Air quality - comparison to predictions	24
5.3	3.2 Air quality - comparison to previous years	25
5.4 N	Noise	27
5.4	4.1 Noise - comparison to predictions	28
5.4	4.2 Noise - comparison to previous years	28
5.5 V	Water	29
5.5	5.1 Groundwater level	29
5.5	5.2 Water monitoring	32
5.5	5.3 Spring Flow	38

5.5.4 Discharge-trial related monitoring	39
5.5.5 Discharge-trial related photo point monitoring	40
5.6 Heritage	40
5.7 Invasive species	40
6. Water management	41
6.1 Water year (1 July 2023 - 30 June 2024)	43
6.2 2017 Water Management Plan	44
6.2.1 Groundwater monitoring requirements	44
6.2.2 Data management protocol	45
6.2.3 Triggers, Actions, Responses and Reporting	46
6.2.4 General Reporting Protocol	48
6.2.5 Surface water quality monitoring and stream health monitoring	48
6.2.6 Site auditing	49
6.2.7 Surface Water Response Plan	51
7. Rehabilitation	52
8. Community	52
8.1 Community meetings	52
8.2 Complaints	53
9. Independent Environmental Audit	54
10. Incidents and non-compliances	62
10.1 Incidents in 2024 reporting period	62
10.2 Non-compliances in 2024 reporting period	62
Schedule 3 Condition 4	62
Overview	62
Causes and consequences	62
Environmental impacts	63
Proposed actions	63
Schedule 3 Condition 27	63
Overview	63
Causes and consequences	64
Environmental impacts	64
Proposed actions	64
10.3 Non-compliances identified in 2023 Annual Review	64
Schedule 2 Condition 13	64
Schedule 5 Condition 4	64
Schedule 5 Condition 8	64

12. References	67
11. Activities in the next reporting period	66
10.4 Regulatory correspondence	65
Schedule 3 Condition 4	64

I. Title block

Name of operation

Ardmore Park Quarry Project

Address

5152 Oallen Ford Road, Bungonia, 2580, NSW

Operator

CEAL Ltd, trading as Multiquip Quarries

Project approval

PA 07_0155 (Mod 3)

Environment licence

13213

Annual review start date

1 January 2024

Annual review end date

31 December 2024

I **Stephen Wall** certify that this audit report is a true and accurate record of the compliance status of ARDMORE PARK QUARRY for the period 1 January 2024 - 31 December 2024 and that I am authorised to make this statement on behalf of MULTIQUIP QUARRIES

Note: The Annual Review is an 'environmental audit' for the purposes of section 9.39(2) of the Environmental Planning and Assessment Act 1979. Section 9.42 provides that a person must not include false or misleading information (or provide information for inclusion in) an audit report produced to the Minister in connection with an environmental audit if the person knows that the information is false or misleading in a material respect. The maximum penalty is, in the case of a corporation, \$1 million and for an individual, \$250,000.

The Crimes Act 1900 contains other offences relating to false and misleading information: section 192G (Intention to defraud by false or misleading statement—maximum penalty 5 years imprisonment); sections 307A, 307B and 307C (False or misleading applications/information/documents – maximum penalty 2 years imprisonment or \$22,000, or both).

Signature of authorised reporting officer(s)

Mr Stephen Wall

Name of authorised reporting officer(s)

7/4/2025 (V1.1)

Date (doc ID)

II. Statement of compliance

Were all conditions of compliance adhered to during the reporting year?

Approval: PA 07_0155 NO

Non-compliances identified during 2024 reporting year.

Approval	Condition	Subject	Status	Reference
PA 07_0155	Schedule 3 Condition 4	Compliance with operating hours		3.5, 10.2
PA 07_0155	Schedule 3 Condition 27	Compliance with transport limits		3.5, 10.2

Table 1: Non-compliance risk level key.

Risk level	Colour	Description
High		Potential for significant environmental consequences regardless of likelihood.
Medium		Potential for serious environmental consequences but unlikely OR potential for moderate environmental consequences with moderate likelihood.
Low		Potential for moderate environmental consequences but is unlikely to occur OR potential for low environmental consequences but is likely.
Administrative		No potential for environmental harm

1. Introduction

1.1 Project description

Ardmore Park Quarry (**the Quarry**) is a sand and hard rock quarry owned and operated by CEAL Ltd (**CEAL**), trading as Multiquip Quarries (**Multiquip**). The project is located 4 km south of Bungonia village and 25 km south east of Goulburn in the Southern Tablelands region of New South Wales. The Quarry falls within the Goulburn-Mulwaree Council (**GMC**) local government area. The regional and local context of the Quarry are presented in Figure 1 and Figure 2, respectively. The current operational disturbance footprint (as of June 2024, added in V2 of this Annual Review) in relation to the development consent boundary is presented in Figure 3.

The Quarry operates under Project Approval 07_0155 (the **Approval** or **Project Approval**) and is designated as a State Significant Development (**SSD**), per the (now repealed) *State Environmental Planning Policy (Major Projects) 2005*, by the Department of Planning, Industry and Environment (**DPIE**), now the Department of Planning, Housing and Infrastructure (**DPHI**), to be referred to throughout this report as **the Department**. The Project Approval was issued by the Minister for Planning in September 2009, with quarrying activities commencing in 2017. The 3rd Modification to the Project Approval was granted in October 2020, but the increase in scale approved under Modification 3 is yet to be implemented, pending the development and approval of required management plans and road upgrades.

The Quarry is approved under Modification 3 for an annual extraction rate of 580,000 tonnes per annum (t/pa); however, as above, the Quarry is currently limited to the previous scale of 400,000 t/pa. The permitted hours of quarrying operations under Modification 3 are between 7 am to 6 pm between Monday to Friday, and 7 am to 1 pm on Saturday. Loading and dispatch of quarried materials are permitted between 5 am to 6 pm Monday to Friday, and 6 am to 1 pm on Saturdays. However, noting Condition 25 of Schedule 3 of the Project Approval, the dispatch of heavy vehicles before 7:00 am is not currently permitted. Neither quarrying nor product loading and dispatch is permitted under the Approval on Sunday or public holidays.




Figure 1: Regional context surrounding the operation.




Figure 2: Near-context surrounding the operation. Zoning shown is as follows: C1, C3, RU1, RU2, RU5.

C	C1	C1 National Parks and Nature Reserves	RU2	RU2 Rural Landscape
C3 C3 Environmental Management		RU5	RU5 Village	
RU1 RU1 Primary Production				




Figure 3: Operational footprint of the Project based on a June 2024 drone survey. Note, some minor georeferencing discrepancies between the drone images and underlying Nearmap basemap may be present. The Development Consent (i.e. Project Approval) boundary is represented in red ("Project Boundary"). The black square is associated with the extent of the drone image file and should be disregarded.

1.2 AR overview

Under Condition 5 of Schedule 5 of the Project Approval, Multiquip must submit an Annual Review (**AR**) to the Department at the end of March of each calendar year. The document describes quarrying and other project related activities conducted in the last 12 months (the **reporting period**). Additionally, key management priorities for the next reporting period are outlined. The reporting period adopted for the purposes of the AR is consistent with the Project Approval and Modification 3, being *the last 12 months* or *the previous calendar* year, respectively. As such, the reporting period for the 2024 AR is 1 January 2024 - 31 December 2024.

The AR functions as the primary mechanism for review of environmental performance for regulators, management, and stakeholders. It details any non-compliances within the reporting period.

This document is submitted on an annual basis to the Department and is published on Multiquip's website once approved [LINK].

1.3 Key personnel

Key personnel responsible for environmental management at the Quarry are presented in Table 2, below.

Table 2: Site contacts.

Name	Role	Email
Stephen Wall	Quarry Manager	stephen.w@multiquip.com.au
4Pillars Environmental Consulting	Environmental Consultants (external)	hello@4pillars.com.au

2. Approvals

2.1 Existing approvals

The Quarry operates under an SSD project approval. In October 2020, the Minister for Planning issued a determination under Section 75J of the *Environmental Planning and Assessment Act 1979 to* approve Modification 3 to PA 07_0155 (**Mod 3**) to increase the extraction area of the quarry, and to modify the permitted operating hours for product transportation and dispatch. As noted above, the expanded provisions under Modification 3 are yet to be implemented and the Quarry is operating within the relevant constraints of Modification 2.

Further to this, the Quarry operates under Environment Protection Licence (**EPL**) 13213, which permits extractive activities and the processing of extractive materials. Several Water Access Licences (**WAL**) are held by the Quarry permitting the utilisation of water from the Goulburn Fractured Rock groundwater aquifer and other near-surface aquifers, and Bungonia Creek.

Wicket Soil Extraction was approved by GMC in 2001 (DA/001/345) and modified in 2015 (MOD/0109/1415), 2019 (MODDA/0031/1920), and 2024 (MODDA/0042/2425). The approval permits the extraction of small quantities of clay rich basalt soils used in the construction of surfaces utilised for sport activities and cricket wickets. A summary of currently active approvals is provided below in Table 3.

Table 3: Summary of Approvals and Licences.

Approval	Consent authority	Issued	Reference
Project approval	NSW Department of Planning, Industry and Environment	2009	PA 07_0155 (Modification 3)
Environment Protection Licence	NSW Environment Protection Authority	2009	13213
Water access licence	Water NSW		30111

Approval	Consent authority	Issued	Reference
	Water NSW		41848
	Water NSW		25390
Wicket Soil Extraction	Goulburn Mulwaree Council	2024	MODDA/0042/2425

2.2 Modifications and amendments

Project Approval PA 07_0155 has been modified on three occasions since the commencement of the Ardmore Park Quarry project to date.

- Modification 1 (2010): Realignment of the entranceway to the quarry to the intersection of Oallen Ford Road and Lumley Road.
- Modification 2 (2013): Approval for local sales of a limited number of quarried products along specified local routes, in addition to the approval principal haul route of Oallen Ford Road and Jerrara Road to the interchange at South Marulan.
- Modification 3 (2020): Approval for expansion of the extraction area by 3.5
 hectares, and to increase the annual production rate from 400,000 to 580,000 t/pa.
 Extension of the operating hours in the morning period.

Environment Protection Licence 13213 (**the EPL**) was most recently varied during the previous reporting period on 10 November 2023. The variation was discussed in the 2023 Annual Review.

3. Operations summary

3.1 Quarrying

The extraction of sand and basalt occurred throughout the reporting period. A total of 244,508 t of this material was dispatched from the quarry for sale, following quarrying, washing, and processing, as appropriate. The main products dispatched from the Quarry to customers were sand and sand related products (approx. 77.5%). Sand from the quarry is primarily purchased by consumers to produce ready-mix concrete for developments in the greater Sydney and Goulburn regions. A lesser proportion of rock, aggregate and road base from processed basalt was sold to customers throughout the year (approx. 22.5%) for landscaping, erosion control, roadmaking, and for ready-mix concrete, with rock sales shown to be decreasing slightly compared to the previous reporting period. Overall, a lower quantity of material was produced in this reporting period as compared to the previous. A summary of production is presented in Table 4.

Sand and basalt resources were predominately derived from two active mining pits in 2024, located in the south-eastern (the "White Pit") and eastern (the "Rock Pit") portions of the quarry, respectively. Removal of overburden in the approved part of the quarry continued in the reporting period, which allows access to the sand extraction pit. Limited

extraction of sand was also undertaken in a third pit (the "Old Pit") in the south-west of the Quarry, following sufficient discharge of water associated with the short-term continuance of the EPL discharge trial increasing access to portions of this pit. A deposit of rock was encountered within the Old Pit that was found to be unsuitable for extraction via conventional means, and as such could not be extracted, hampering operations. As the project progresses, it is expected that the extent of the three active quarrying areas will join.

Table 1: Production summary	Itable taken from the October	2015 Annual Review Guideline)
Table 4: Production summary	Trapie taken from the October	ZUTO Annual Keview Guideline).

Material	Approved limit (source)	Previous reporting period (actual)	This reporting period (actual)	Next reporting period (forecast)
Waste Rock / Overburden	N/A	N/A	N/A	N/A
ROM Coal / Ore	N/A	N/A	N/A	N/A
Coarse reject	N/A	25,647	24,451	~40,000 t
Fine reject (Tailings)	N/A	25,647	24,451	~40,000 t
Saleable product	580,000 t (Mod 3)	256,470	244,508	400,000 t

3.2 Compliance and returns

The Annual Return for EPL 13213 was lodged with the NSW EPA by 19 October 2024, covering the 2023-24 licence year of 21 August 2023 - 20 August 2024. Five non-compliances were raised in the Annual Return, relating to the following issues:

- Truck movements outside of the EPL-hours of operations.
- The EPL requires activities to be carried out in accordance with an outdated Water Management Plan, whereas activities are actually carried out in accordance with an updated plan.
- Monitoring of groundwater (flow + water quality) at one location not completed due to damage to bore.
- Breaches of terms of the SOEE associated with the discharge trial.
- Delays in submission of reports associated with the discharge trial.

Further information about the above non-compliances and the corresponding EPA actions is available on the POEO Public Register.

Non-compliance with two conditional requirements of PA 07_0155 (Mod 3) during the reporting period were identified and are discussed in further detail in Section 10 of this Annual Review, relating to the following issues:

• Truck movements outside of operating hours and in excess of permitted hourly limits.

3.3 Roadworks

No roadworks were undertaken by Multiquip during the reporting period.

3.4 Truck movements

Truck movements are tracked and recorded via the use of the on-site weighbridge. Each month, the data for the preceding month is reviewed and assessed, with a summary report completed and published on the company website. The truck movement summary for the reporting period is presented in Table 5, below.

Table 5: Truck movement summary, 2024.

Month	Total truck movements (In + Out)	Daily average truck movements (In + Out)
Jan	604	27
Feb	1004	40
Mar	956	38
Apr	972	41
May	1006	40
Jun	873	36
Jul	1114	41
Aug	942	35
Sep	990	40
Oct	998	38
Nov	1214	49
Dec	782	41
2024 Total	11455	

3.5 Compliance with transport limits

Weighbridge records for 2024 were reviewed to determine compliance with operating hours and transport limits, which are defined in Condition 4 of Schedule 3 and Condition 27 of Schedule 3 of the Project Approval, respectively. It is noted that a number of non-compliances were identified in the 2023 reporting period, which were presented in the 2023 Annual Review and are summarised below.

During the 2024 reporting period, a total of 11,455 truck movements occurred, over a total of 294 days. Of these movements, the project was found to have a high degree of compliances, with the following exceptions.

28 movements (0.24% of total movements) occurred outside of the permitted operating hours i.e. later than 1 pm on a Saturday, or 6 pm on a weekday. These movements outside of the permitted operating hours occurred across 14 days, an average of two movements (i.e. a single truck entering and exiting) per day.

80 movements were identified (0.70% of total movements) which were in excess of the permitted hourly limits. These movements occurred across 46 days. Of these, the vast majority (93%) were found to have occurred in the 7-8 am period.

In the 11 December 2024 response to the Show Cause, the majority of the above non-compliances were notified to DPHI, with the final figures for 2024 (as presented above) notified as non-compliances to DPHI on 4 April 2025.

The number of non-compliances as identified above was lower than in the 2023 reporting period.

There were no exceedances with the daily limits for truck movements for either weekdays or Saturdays, as presented in Condition 27(a) and (b) of Schedule 3.

Improvements to weighbridge management

A number of improvements to weighbridge and truck movement management were included in the 11 December 2024 response to the Show Cause, which are presented in Table 6, below, along with their current status.

Table 6: Improvements presented in the 11 December 2024 response to the Show Cause and current status.

Proposed improvement	Status as of 2024 Annual Review
Obtaining a new weighbridge system from GTick.	Underway Order has been placed with GTick, lead- time approx. 8 weeks. Expected installation mid-May.
Training of allocators and other key personnel about compliance with consent conditions relating to truck movements.	Completed Toolbox talk was conducted on 10 December 2024.
Performing daily reviews of weighbridge data to assess any actual, or near, non-compliances that day. If so, implementation of training and disciplinary action as necessary.	Ongoing This is conducted daily.
Resolving outstanding requirements of the consent, to permit earlier weighbridge operations and alleviate pressure on the 7am to 8am time period particularly, as well as generally throughout the day.	Underway This is contingent on the approval of management plans and other items, as discussed elsewhere in this Annual Review.
Consideration of an amendment to consent conditions, to make compliance more straightforward.	Not yet considered This is a potential future action. Not considered a priority at this time.

2023 Annual Review

For comparison, a summary of compliance as reported in the 2023 Annual Review is presented below:

- 50 days on which a non-compliance with the transport limits was identified.
 - o 10 weekdays where truck movements occurred after 6 pm
 - o Five Saturdays where truck movements occurred after 1 pm
- 102 truck movements outside permitted hourly limits (0.83% of total movements).
- Zero instances where the limits for daily total movements were exceeded.

4. Activities proposed in the previous AR

Activities that were expected to occur in 2024 as listed in the 2023 Annual Review are as follows, along with their status.

Table 7: Activities proposed in the 2023 Annual Review and current status.

Proposed activity	Status
Continuation of mining activities at the site. Indicatively expected to be 400,000 tpa to be increased to 580,000 tpa when appropriate documentation etc. is approved Further rehabilitation and landscaping of visual bunds, pending approval from DPE	Completed Mining activities continued during the reporting period, remaining below the 400,000 tpa threshold. Not completed / No change since previous AR Ongoing with DPHI.
 Monitoring SWL of bores monthly Deposited dust monthly Water sampling quarterly and annually Particulate matter continuously (assessed monthly) Noise twice annually Discharge sampling (characterisation and validation) as required Discharge water quality sampling monthly during discharge Ambient water quality sampling monthly during discharge 	All monitoring was carried out as required, including monitoring associated with the EPL discharge trial, excepting some minor non-compliances, as discussed in Section 3.2 Compliance and returns. Noise monitoring was carried out twice, in March and November 2024. Monitoring results are presented in Section 5.
Implementation of additional dust management measures arising from the DMCA, following agreement with EPA.	Completed Two dust management measures were required for implementation during 2024, related to water cart usage and particulate matter alarms. Both of these were implemented as required.
Implementation of weed control program(s)	Completed Weed control programs were conducted for Blackberry, St Johns Wort, and Serrated Tussock.
Relocation of weather station to allow for extension of quarrying	Not completed - Not required It was identified that this was not required, as quarrying activities were not hampered by the location of the weather station.
Submission of modification to Project Approval (Modification 4) to ensure activities align with Approval	Not completed / No change since previous AR Postponed, awaiting conclusion of the compliance investigation and associated sentencing.
Attendance at all Community Consultative Committee (CCC) meetings	Completed

Proposed activity	Status
	One CCC meeting was held during the
	reporting period, in May 2024.
Submission of EPL variation to remove	Not completed / No change since
identified bores from EPL	previous AR
	Postponed, as EPL variations related to
	the additional dust management
	measures arising from the DMCA were
	underway.
Close-out of Development Control Order	Not completed / No change since
	previous AR
	Expected to occur early-mid 2025, in
	light of the conclusion of the compliance
C I I I I I I I I I I I I I I I I I I I	investigation and associated sentencing.
Completion and lodgement of Modification	Not completed
3 Environmental Management Plans	Discussions with the Department
	regarding the management plans was ongoing during the reporting period.
	The Department's position on reviewing
	was unchanged and would not review
	plans until completion of legal
	proceedings. Uploaded management
	plans were withdrawn at DPHI's request
	in August 2024.
Continued discharge of water from Old Pit	Completed
in accordance with discharge trial extension	Discharge in accordance with the
until empty, and follow-up earthworks	discharge trial extension commenced on
	10 January 2024 and ceased on 9 May
	2024. The Old Pit was not completely
	emptied during this period.
Submission of Enforceable Undertaking -	Not completed
associated with resolution of DCO	The DCO was not resolved during the
	reporting period. This was understood to be due to its association with the legal
	proceedings.
	As discussions between the Proponent
	and DPHI could not come to a suitable
	resolution regarding the contents and
	commitments to be included in the
	Enforceable Undertaking, it was opted to
	go through the compliance investigation
	and associated sentencing, rather than
	pursue the Enforceable Undertaking.
Finalise Voluntary Planning Agreement	Not completed / ongoing
(VPA) with Goulburn Mulwaree Council and	Discussions with the Department and
provide update to DPE accordingly, as per	Goulburn Mulwaree Council (Council)
Schedule 2 Condition 13 of the Project	were ongoing during the reporting
Approval and DPE's 1 February 2023	period. A non-compliance was raised by
extension approval	Multiquip on 22 March 2024. The
	Department requested an update on 30 October 2024, with an update being
	October 2024, with an update being

Proposed activity	Status
	provided on 21 November 2024. A meeting between Multiquip and Council was held on 5 December 2024. Further advancement is expected in 2025.
	advancement is expected in 2025.

5. Environmental performance

5.1 Monitoring points




Figure 4: Monitoring locations.

5.2 Meteorological data

The average monthly temperatures recorded by the on-site weather station (location shown in Figure 4, "PM10_W") ranged between 8°C to 20°C throughout the reporting period. The temperature range observed is heavily influenced by the Quarry's elevation within the Southern Tablelands Region. Average temperature is presented in Figure 5, along with site data from 2023, showing the relative consistency across the two years. 2024 data from the Goulburn weather station of the NSW Government's New South Wales Air Quality Monitoring Network¹ are also presented, and are consistent with the on-site data.

¹ https://www.airquality.nsw.gov.au/air-quality-data-services/data-download-facility




Figure 5: Average monthly temperature recorded at the site, 2024 and 2023, and the NSW Government's Goulburn weather station.

Data collected during 2024 indicated an increased level of rainfall in comparison to 2023, with approximately 1103 mm of rain recorded compared to 773 mm observed in the previous year (Figure 6). This was similar to 2021, when 1013 mm of rainfall was observed. It was noted that 2024 data from the Goulburn weather station was generally consistent with on-site data, however with some notable differences e.g. May, August. It was identified during the reporting period that there were some data fault and sensor errors with the on-site weather station that may have attributed to this. The supplier for the station was contacted for their advice and to make repairs where required. The weather station continued to operate during this time.




Figure 6: Total monthly rainfall recorded at on-site weather station, comparison of 2023 and 2024.

Daily rainfall data from the on-site weather station has been presented in Figure 7, and - along with monthly data - can be used to assess trends in monitoring data.




Figure 7: Daily rainfall recorded at on-site weather station.

5.3 Air quality

Air quality emissions from the Project are managed through the following actions:

- Regular application of water to haul roads using a water cart to increase soil moisture and prevent the generation of dust;
- Application of water to hard-rock processing plant feed hopper and crushers;
- Locating the crushing plant within the hard rock processing area of the quarry, a significant distance from neighbouring properties; and
- Avoiding stripping soils during windy periods.

To ensure that air quality emissions are sufficiently controlled, monitoring for deposited dust and particulate matter are undertaken.

On 27 September 2023, EPL 13213 was varied by the EPA to require a Dust Management Capacity Assessment (DMCA) to be undertaken (Conditions U3.1, U3.2 and U3.3). The intent of the DMCA was to assess the capacity of the Premises to prevent or minimise the generation and movement of dust emissions and identify options for improving dust control at the Premises. 4Pillars Environmental Consulting Pty Ltd (4Pillars) was engaged to undertake the DMCA, with the final report submitted to the EPA on 11 December 2023. A number of additional dust management measures were identified in the DMCA, to reduce dust emissions and limit the risk of air quality impacts on the environment and nearby receivers. These were subsequently added to the EPL for the Site, of which the following were required to be implemented during 2024:

- By 15 November 2024: Utilisation of water cart/s to prevent the emittance of dust off-site from all operational areas (including haul roads) in dry weather or dust generating conditions.
 - o This condition was complied with.
- By 29 November 2024: Establishment of real-time alert system for the particulate matter remote sensors.
 - o This condition was complied with.

Deposited Dust

The Quarry undertakes monthly deposited dust monitoring as per the requirements of EPL 13213. The air quality monitoring network established around the Quarry includes four deposited dust gauges located at the quarry site, and at nearby receivers, to determine whether quarry activities generate dust in excess of the permitted air quality limits. The deposited dust gauges are situated in locations clear of obstructions which may interfere with the collection of fugitive dust emissions at the established monitoring points. As per Figure 4, the "Lochmoor Lodge" and "Osiers" dust gauges are located to the west of the extraction area. The "Front Entrance" dust gauge captures emissions at the entrance to the site, and the "Inverary Park" dust gauge monitors dust emissions at the adjacent neighbouring premises to the north-eastern side of the active extraction area.

Samples collected are analysed at a NATA-accredited laboratory, with the insoluble solids fraction of the total sample used to assess compliance with the air quality criteria specified in Condition 7 of Schedule 3 of the Mod 3 Approval (4 g/m²/month total, 2 g/m²/month incremental). Results for 2024 are presented in Figure 8.




Figure 8: 2024 Deposited dust (insoluble solids) results. Limit of 4 g/ m^2 /month for total impact of particulate matter emissions generated by the project is presented as a green line.

As shown in the graph, there were a total of two instances where the primary results for insoluble solids were greater than the total limit, across two months (May, September).

To inform an assessment of the obtained results, a review of meteorological data and the composition of the matter as analysed by the lab was undertaken, along with aerial imagery of surrounding properties, and site activities. The outcome for each of the results is summarised in Table 8. While the limit in the Project Approval is for insoluble solids, these are not necessarily directly correlated with quarrying activities, as this result includes both combustible matter and ash. Combustible matter includes organic material (e.g.

pollen, grass), while the ash fraction accounts for the non-combustible mineral content (i.e. soil dust) which could be caused by soil disturbance during quarrying activities.

Table 8: Review of elevated deposited dust results, 2024.

Month	Location	Cause	Exceedance generated by Project?
May	Inverary Park	High proportion of combustible matter in the sample, ash fraction below limit.	No
September	Front Entrance	High proportion of combustible matter in the sample. Ash fraction above limit. Wind observations from on-site weather station were assessed - the majority of wind experienced during the period came from western directions (i.e. from off-site and the road), with only approx. 17% from the direction of the quarry. Based on the wind conditions observed, exceedances in other dust gauges would be expected, however these were all considerably below the project criteria. Quarry activity remained at a steady scale, and no notable increases in crushing occurred which would have promoted excessive dust. Likely sources considered to be the road or neighbouring properties to the west, where agricultural activities (including soil preparation) were underway.	No

Overall, data for all other months, and the long-term average deposited matter results (Table 9) indicate that the project has a high degree of compliance with the performance criteria.

Table 9: Average deposited dust (insoluble solids) results for 2024, across all sampling points. Despite nominal exceedances, the annual averages for all sampling points were compliant with the prescribed limits.

Monitoring location	Insoluble solids (g/m²/month)	
Monitoring location	Annual Average (2024)	
Inverary Park	1.3	
The Osiers	0.6	
Lochmoor Lodge	0.6	
Front Entrance 1.8		
Limit (4 g/m²/month)		

Particulate matter

Air quality criteria for particulate matter emissions generated by the project are specified in Condition 7 of Schedule 3 of the Project Approval, with limits prescribed for Particulate matter <10 μ m (PM₁₀) and Particulate matter <2.5 μ m (PM_{2.5}). Over an annual averaging period, the limits for total impacts (i.e. incremental increases in concentrations due to the

project plus background concentrations due to all other sources) are $25 \,\mu g/m^3$ for PM_{10} and $8 \,\mu g/m^3$ for $PM_{2.5}$. Over a 24-hour averaging period, the limits for incremental impacts (i.e. incremental increases in concentrations due to the project on its own) are $50 \,\mu g/m^3$ for PM_{10} and $25 \,\mu g/m^3$ for $PM_{2.5}$.

Particulate matter emissions are measured by two Sensirion SPS30 Particulate Matter Sensors installed with Atmos 22 and Atmos 41 weather stations, which have been established at two locations within the Quarry Site - PM (E) and PM (W), respectively - as shown on Figure 4. These sensors are real-time optical particle counters (OPCs), which obtain measurements based on the incoming particles scattering the incoming light, the extent of which is then detected by a photodiode and converted into real-time particle count and mass concentration values. This allows the sensors to record the levels of various particulate matter fractions simultaneously, including PM1.0 (0.3 to 1.0 µm), PM2.5 $(0.3 \text{ to } 2.5 \mu\text{m})$, PM4.0 $(0.3 \text{ to } 4.0 \mu\text{m})$, and PM10 $(0.3 \text{ to } 10.0 \mu\text{m})$, rather than requiring manual collection and analysis of filters for individual fractions. The weather stations where the particulate matter sensors are installed record a variety of parameters including temperature, wind and gust speed, rainfall, humidity, and wind direction. All of the data is automatically and continuously uploaded to an online portal, from which it can be observed or downloaded. The particulate matter data gathered can then be compared to the obtained weather data, to determine if and how the weather conditions influence the particulate matter readings obtained.

The raw data from each unit is downloaded and analysed monthly, to allow comparisons with the prescribed criteria. Furthermore, as required by the EPL, a real-time alert system was established during the reporting period to send an email at a trigger value for readings >12 μ g/m³. It is noted that this trigger value is conservative, at a level of 24% and 48% of the 24-hour averaging limit for PM₁₀, and PM_{2.5}, respectively.

The data for 2024 as a 24 hour average is presented in Figure 9 and Figure 10 for PM_{10} and $PM_{2.5}$, respectively, with the Project Approval limits included on the graphs. As shown, while particulate matter levels recorded by both units were slightly elevated at times, they were generally stable, and remained well below their respective limits throughout the year. It is noted that this data is for total particulate matter (including background levels), rather than directly attributable to quarrying operations.




Figure 9: 2024 PM₁₀ data for both units, 24-hour averaging, with Project Approval limit.




Figure 10: 2023 PM_{2.5} data for both units, 24-hour averaging, with Project Approval limit.

All of the data collected was also assessed to determine the particulate levels on an annual averaging basis, for comparison with the prescribed limits, as shown in Table 10. The levels recorded at both monitoring locations were compliant with the limits.

Table 10: 2023 PM_{2.5} and PM₁₀ data for both units, annual averaging, with Project Approval limits.

Monitor	Pollutant (μg/m³)		
Widiltor	PM2.5	PM10	
PM10-E	1.91	2.06	
PM10-W	2.67	3.13	
Limit (Annual average)	8	25	
Compliant?	Yes	Yes	

5.3.1 Air quality - comparison to predictions

Condition 5b(iv) of Schedule 5 of the Project Approval requires that a comparison of monitoring results to the "relevant predictions in the documents listed condition 2 of Schedule 2" is included in the Annual Review. Relevant predictions relating to air quality were identified in the July 2008 Environmental Assessment for the Modified Ardmore Park Quarry Project, prepared by R.W. Corkery & Co Pty Limited (the 2008 EA) and the December 2017 Environmental Assessment for Modification 3 to PA 07_0155 (Ardmore Park Quarry), prepared by R.W. Corkery & Co. Pty Limited (the 2017 EA). No relevant predictions for air quality were identified in the other documents listed in Condition 2 of Schedule 2.

Deposited dust

The predictions in the 2008 EA for the annual average of dust deposition were that across the residences assessed, the Background + Increment (i.e. total) values would range from 2.3-2.7 g/m²/month, below the Project Goal of 4.0 g/m²/month. The annual average deposited dust (insoluble solids) results for 2024 are presented above in Table 9, and show the results at all four assessed dust gauges as between 0.6-1.8 g/m²/month, all of which were below the predicted values. A comparison of the 2024 values to the predicted values is presented in Table 11, below.

Table 11: Average deposited dust (insoluble solids) results for 2024 as compared to predictions.

Manitoring location	Insoluble solids (g/m²/month)		
Monitoring location	2024 Average	Predictions (2008 EA)	
Inverary Park	1.3	2.7	
The Osiers	0.6	2.3	
Lochmoor Lodge	0.6	2.7	
Front Entrance	1.8	2.3	

The 2017 EA noted that the proposed modification did not provide for changes to operations likely to significantly increase air emissions. As such, no alternative values were presented for comparison.

PM10

The predictions in the 2008 EA for PM10 were that "with respect to the 24-hour average, the maximum PM10 concentrations is predicted to be less than the site-specific goal $50 \,\mu\text{g/m}^3$ at all assessment locations for the three scenarios considered". As presented in Figure 9, the maximum 24-hour average concentration of PM10 throughout the reporting period was 17.6 $\,\mu\text{g/m}^3$, in line with the predictions.

The 2017 EA noted that the proposed modification did not provide for changes to operations likely to significantly increase air emissions. As such, no alternative values were presented for comparison.

PM2.5

The predictions in the 2008 EA for PM2.5 were that the worst case 24-hour average levels were predicted to be in the order of 15 μ g/m³ and annual average PM2.5 predicted to be in the order of 6 μ g/m²". (Note: "m²" here is believed to be a typo and should read "m³"). As presented in Figure 9, the maximum 24-hour average concentration of PM2.5 throughout the reporting period was 12.2 μ g/m³, with the maximum annual average concentration across both monitoring devices of 3.1 μ g/m³ (PM10-W, Table 10). Both values are in line with the predictions.

The 2017 EA noted that the proposed modification did not provide for changes to operations likely to significantly increase air emissions. As such, no alternative values were presented for comparison.

5.3.2 Air quality - comparison to previous years

Condition 5b(iii) of Schedule 5 of the Project Approval requires that a comparison of monitoring results to the "monitoring results of previous years" is included in the Annual Review.

Deposited dust

Results for deposited dust levels (as insoluble solids) for the reporting period compared to previous years are presented in Figure 11. Due to issues with graphing historical data, data earlier than 2021 has not been included. While some elevated readings were observed during the reporting period, values were generally similar to previous years.




Figure 11: 2021-2024 deposited dust (insoluble solids) results. Limit of 4 g/m²/month for total impact of particulate matter emissions generated by the project is presented as a green line.

PM10

Results for PM10 for the reporting period compared to previous years are presented in Figure 12. Across both units, levels were generally consistent with previous years, and lower than 2021.




Figure 12: PM10 data for both units from 2021-2024, 24-hour averaging, with Project Approval limit.

PM2.5

Results for PM2.5 for the reporting period compared to previous years are presented in Figure 13. Across both units, levels were generally consistent with previous years, and lower than 2021.




Figure 13: PM2.5 data for both units from 2021-2024, 24-hour averaging, with Project Approval limit.

5.4 Noise

Site noise is managed through the use of appropriately maintained equipment, commitment to permitted operating hours, and the construction and maintenance of bund walls around activities. Machinery is located in areas where potential transmission of noise to off-site receivers is limited. Community complaints regarding noise are investigated and acted upon, with a lack of these suggesting an appropriate level of noise generation. Compliance with noise criteria is confirmed through regular noise monitoring assessments performed by an external consultant.

Pulse White Noise Acoustics Pty Ltd were engaged to conduct attended noise monitoring in March and November 2024. A summary of the outcomes of the monitoring undertaken during each assessment was uploaded to the Multiquip website upon completion. Noise measurements are obtained from neighbouring properties, or accessible public land close to the receivers, as appropriate. The summary of noise results obtained is presented in Table 12. The project was considered compliant with noise criteria during all monitoring periods. Noise monitoring will continue throughout 2025.

Table 12: Summary of noise results, 2024.

Date	Location (EPL #)	Average Estimated Quarry L(A)eq 15 min	Compliance
	Damar Lodge (4)	≤40	Yes
11/03/2024	The Osiers (5)	<30	Yes
	Lochmoor (6)	<30	Yes

Date	Location (EPL #)	Average Estimated Quarry L(A)eq 15 min	Compliance
	5194 Oallen Ford Road	<30	Yes
	Inverary Park (3)	<30	Yes
	28 King Street	<25	Yes
	328 Jerrara Road	46	Yes
	989 Jerrara Road	46	Yes
	The Osiers (5)	≤30	Yes
	Lochmoor (6)	<30	Yes
	5477 Oallen Ford Road	47	Yes
20/11/2024	Inverary Park (3)	<30	Yes
20/11/2024	5100 Oallen Ford Road	<35	Yes
	28 King Street	53	Yes
	989 Jerrara Road	47	Yes
	328 Jerrara Road	49	Yes

5.4.1 Noise - comparison to predictions

Condition 5b(iv) of Schedule 5 of the Project Approval requires that a comparison of monitoring results to the "relevant predictions in the documents listed condition 2 of Schedule 2" is included in the Annual Review. Relevant predictions relating to noise were identified in the July 2008 Environmental Assessment for the Modified Ardmore Park Quarry Project, prepared by R.W. Corkery & Co Pty Limited (the 2008 EA) and the December 2017 Environmental Assessment for Modification 3 to PA 07_0155 (Ardmore Park Quarry), prepared by R.W. Corkery & Co. Pty Limited (the 2017 EA). No relevant predictions for noise were identified in the other documents listed in Condition 2 of Schedule 2.

In all cases, the noise levels recorded during the reporting period were consistent with the predictions presented in the 2008 EA, and below the assessed criteria. The 2017 EA noted that it was considered unlikely that the proposed modifications would result in increases to noise levels which would exceed criteria.

5.4.2 Noise - comparison to previous years

Condition 5b(iii) of Schedule 5 of the Project Approval requires that a comparison of monitoring results to the "monitoring results of previous years" is included in the Annual Review. Results of noise monitoring of quarry activities from 2021 to 2024 at monitoring locations intended to be representative of select Noise Assessment Location Residences as identified in the EPL are presented in Table 13. As shown, noise levels during monitoring have been consistently low, and compliant with required limits. As shown in the table, not all residences were directly assessed during each monitoring event, however the engaged noise consultants were confident that the results obtained were representatively sufficient to inform an assessment of compliance of the Project against the requirements. Each value presented represents the value for a single monitoring session.

Table 13: Comparison of noise results for quarry-generated noise, 2021-2024.

	Estimated Contribution of Project (L(A)eq 15 min)						
Monitoring month	Residence 1	Residence 3	Residence 4	Residence 6	Residence 9		
Feb-21	<23	<20	<33	<33	-		
Aug-21	-	<33, <32	-	<27, <27	-		
Feb-22	-	<33, <33	-	<30, <30	-		
Nov-22	-	<30	≤40	<35	<30		
Aug-23	-	<30	≤40	<30	<30, <30		
Mar-24	-	<30	≤40	<30	-		
Nov-24	-	<30	-	<30	-		

5.5 Water

5.5.1 Groundwater level

Measurement of standing water level (SWL) is carried out on a monthly basis at 10 monitoring bores on and around the site as per the requirements of EPL 13213. Monitoring data collected indicates that - while groundwater levels fluctuate from month-to-month - the standing water levels are generally stable and constant over time.

A summary of standing water level for all bores measured throughout the reporting period is presented below in Table 14, with monthly measurements presented in Figure 14.

One unusual value related to BHAP6 (November 2024) is considered likely to be attributed to the influence of the pump operating in the bore during/prior to measurement the monitoring, noting that the level stabilised during the following reading.

As originally reported in the 2021 Annual Review, bore BHS6 (EPL Point 14) was damaged and could therefore not be monitored during the 2024 reporting period. An EPL variation to remove the monitoring requirements associated with this bore from the EPL was intended to be submitted during the reporting period, but was not possible due to other priorities with the EPL, as discussed in Section 4.

Table 14: Summary of bore standing water levels during 2024. "Min." refers to the lowest value recorded, i.e. the shallowest reading. "Max." refers to the highest value recorded, i.e. the deepest reading. *Considered likely to be influenced by pumping of bore during/prior to measurement.

Name (EPL #)	Min. of SWL (m)	Max. of SWL (m)	Average of SWL (m)
BH6 (14)	14.36	14.60	14.47
BHAP1 (5)	6.80	7.69	7.24
BHAP10 (8)	26.02	26.60	26.31
BHAP5 (6)	53.63	54.57	54.09
BHAP6 (7)	61.09	82.03*	64.15
BHS1 (18)	9.97	10.40	10.15
BHS2 (19)	5.49	5.92	5.64
BHS3 (20)	3.80	4.61	4.35
BHS4 (21)	4.17	4.70	4.46
BHS5 (22)	6.32	7.24	6.63




Figure 14: Monthly bore standing water level measurements during 2024. The reduction in SWL of BHAP6 during November is considered likely to be influenced by pumping of bore during/prior to measurement.

The standing water level at BHAP6 (the production bore) fluctuated slightly throughout the reporting period, but the final measurement (63.47 m, December 2024) was only 0.67 m deeper than the first measurement (62.8 m, January 2024). The measured height at the end of the reporting period remained higher than the measurements taken during the 2019 reporting period (e.g. 67.09 m, November 2019). Monthly measurements are presented in Figure 15.




Figure 15: Standing water level BHAP6 (Production Bore). Note, measurements believed to be erroneous due to the influence of the pump (November 2024) have been removed from the graph.

Comparison to previous years

Condition 5b(iii) of Schedule 5 of the Project Approval requires that a comparison of monitoring results to the "monitoring results of previous years" is included in the Annual Review. A comparison of standing water level (SWL) readings obtained during the reporting period to previous years (since 2020) is provided in Figure 16, below, and in Figure 15 for BHAP6. Although fluctuations across bores can be observed, the levels remain generally consistent with data from previous years.




Figure 16: Standing water level since 2020. Note BHAP6 is not shown as it is presented in Figure 15, and BHAP5 is not shown due to the change in SWL observed following the relining of the bore (refer to 2023 Annual Review).

5.5.2 Water monitoring

Water monitoring across the project site is undertaken in accordance with the 2017 Water Management Plan and requirements of the EPL, with samples collected quarterly from six of the 10 bores, and annually from the remaining four bores. Samples are collected from the three springs quarterly or during periods of flow, as appropriate. This monitoring regime will continue in 2025. In 2024, all samples were obtained as required, excepting from bore BHS6, which was damaged as detailed above, and sand bores BH1-BH5, which were previously destroyed in accordance with extraction activities, and replaced with the BHS1-BHS6 bores. The monitoring schedule of all analytes is presented in Table 15, below.

Table 15: Monitoring schedule undertaken during the reporting period. *Access issues during the April 2024 monitoring session required that supplementary monitoring was conducted at BH6 and Southern Spring during May 2024. **Ionic Balance out of acceptable limits for some samples and therefore not calculated.

Analyte / Aquifer	Hard Rock (BHAP1, BHAP5, BHAP6, BHAP10)	Sand (BH6*, BHS1- 5)	Springs (Phils, Southern*, Western)
Standing Water Level (SWL)	Monthly	Monthly	N/A
Flow	N/A	N/A	Monthly
рН	Quarterly - January, April, July, October	Quarterly - January, April, July, October	Quarterly - January, April, July, October
Electrical Conductivity	Quarterly - January, April, July, October	Quarterly - January, April, July, October	Quarterly - January, April, July, October
Total Dissolved Solids	Quarterly - January, April, July, October	Quarterly - January, April, July, October	Quarterly - January, April, July, October
Calcium	January, October	Quarterly - January, April, July, October	Quarterly - January, April, July, October
Chloride	January, October	Quarterly - January, April, July, October	Quarterly - January, April, July, October
Iron	January, October	Quarterly - January, April, July, October	Quarterly - January, April, July, October
Magnesium	January, October	Quarterly - January, April, July, October	Quarterly - January, April, July, October
Manganese	January, October	Quarterly - January, April, July, October	Quarterly - January, April, July, October
Potassium	January, October	Quarterly - January, April, July, October	Quarterly - January, April, July, October
Sodium	January, October	Quarterly - January, April, July, October	Quarterly - January, April, July, October
Sulfate	January, October	Quarterly - January, April, July, October	Quarterly - January, April, July, October
Alkalinity	January, October	Quarterly - January, April, July, October	Quarterly - January, April, July, October
lonic Balance**	January	Quarterly - January, April, July, October	Quarterly - January, April, July, October
Arsenic Cadmium	January, October January, October	January, October January, October	January, October January, October

Analyte / Aquifer	Hard Rock (BHAP1, BHAP5, BHAP6, BHAP10)	Sand (BH6*, BHS1- 5)	Springs (Phils, Southern*, Western)
Chromium	January, October	January, October	January, October
Copper	January, October	January, October	January, October
Lead	January, October	January, October	January, October
Mercury	January, October	January, October	January, October
Nickel	January, October	January, October	January, October
Zinc	January, October	January, October	January, October
BTEX	Not analysed	Quarterly - January, April, July, October	Quarterly - January, April, July, October
TRH	Not analysed	Quarterly - January, April, July, October	Quarterly - January, April, July, October

The below tables present a summary of the average groundwater monitoring results across 2024 calculated from the four regular quarterly sampling events. They have been summarised into general water properties (Table 16), anions and cations (

Table 17), and hydrocarbons (Table 18), to allow for comparison with previous Annual Reviews.

The results are generally comparable with observations from the previous reporting period across all bores.

All hydrocarbon results were at levels below detection/reporting.

Sampling results for the below analytes do not indicate any evidence of impact upon groundwater quality as a result of quarrying activities.

In the April 2024 monitoring event, BHAP6 returned an extremely high value for Total Dissolved Solids (37,900 mg/L) as compared to usual readings (~500 mg/L). It was expected that this was a consequence of silt within the sample due to a recent agitation of the water column during pumping of the bore for operational use. The subsequent sampling event in July showed a return to a normal TDS value (565 mg/L). Accordingly, the average value when the April result is excluded has also been presented in Table 16. Future sampling events are intended to avoid sampling following recent pumping, where possible.

Table 16: General properties, average across 2024. *Average excluding April 2024 result, as discussed in text.

Name	Sulfate (mg/L)	EC (μS/cm)	рН	TDS (mg/L)
BH6	3.3	798.0	7.5	599.8
BHAP1	21.5	1352.5	7.0	1088.5
BHAP10	6.9	415.3	7.0	316.0
BHAP5	9.6	703.0	7.6	407.3
BHAP6	10.1	851.8	7.7	9845.0 / 493.3*
BHS1	2.0	291.5	6.3	341.8
BHS2	3.3	283.8	6.6	193.8
BHS3	3.0	517.8	6.6	314.3
BHS4	3.9	787.0	7.6	437.8

Name	Sulfate (mg/L)	EC (μS/cm)	рН	TDS (mg/L)
BHS5	5.5	1207.5	7.6	675.3
BHS6				
Phils Spring	14.0	1230.0	7.7	732.5
Southern Spring	3.3	496.5	7.2	322.3
Western Spring	1.8	1192.0	7.9	741.3

Table 17: Anions and cations, average across 2024.

Name	Ca mg/L	Cl mg/L	K mg/L	Na mg/L	Mg mg/L
вн6	51.0	86.8	0.8	46.5	53.0
BHAP1	162.5	450.0	3.3	97.0	5.0
BHAP10	4.2	67.5	3.6	72.5	5.3
BHAP5	51.5	55.0	3.4	56.0	33.5
BHAP6	72.5	61.5	1.1	60.0	30.0
BHS1	11.0	69.0	2.1	23.0	13.0
BHS2	6.3	57.8	1.1	35.5	10.1
BHS3	8.9	138.0	0.675	68.8	16.8
BHS4	51.3	50.3	0.9	34.0	64.0
BHS5	62.8	129.0	0.525	79.0	93.0
BHS6					
Phils Spring	56.5	182.8	0.875	87.0	89.8
Southern Spring	23.3	66.8	0.55	42.0	25.3
Western Spring	39.25	258	1.4	127.75	62

Table 18: Hydrocarbons, average across 2024.

Name	TRH µg/L	Benzene µg/L	Toluene μg/L	Ethyl benzene μg/L	xylene μg/L
BH6	BDL	BDL	BDL	BDL	BDL
BHAP1	BDL	BDL	BDL	BDL	BDL
BHAP10	BDL	BDL	BDL	BDL	BDL
BHAP5	BDL	BDL	BDL	BDL	BDL
BHAP6	BDL	BDL	BDL	BDL	BDL
BHS1	BDL	BDL	BDL	BDL	BDL
BHS2	BDL	BDL	BDL	BDL	BDL
BHS3	BDL	BDL	BDL	BDL	BDL
BHS4	BDL	BDL	BDL	BDL	BDL
BHS5	BDL	BDL	BDL	BDL	BDL
BHS6					
Phils Spring	BDL	BDL	BDL	BDL	BDL
Southern Spring	BDL	BDL	BDL	BDL	BDL
Western Spring	BDL	BDL	BDL	BDL	BDL

Comparison to previous years

Condition 5b(iii) of Schedule 5 of the Project Approval requires that a comparison of monitoring results to the "monitoring results of previous years" is included in the Annual Review. A comparison of water monitoring data obtained during the reporting period to previous years (since 2021) is provided in Table 19 and Table 20, below. All readings for hydrocarbons across all monitoring points were below the laboratory detection limit (BDL), across the reporting period and the three previous years and have hence not been tabulated. Although all values fluctuated slightly, data obtained during the reporting period was found to be generally consistent with data from previous years, with the following observations:

- A return to 2022-levels for cations/anions in BHAP1 and BHAP5 that had reduced in the previous reporting period (calcium, chlorine, sodium), and BHS5 (chlorine).
- A return to 2022-levels for cations/anions in Western Spring (chlorine, sodium, magnesium)
- Values of sulfate, electrical conductivity, and total dissolved solids in BHAP1 that
 were consistent with the previous reporting period, which was noted to be
 elevated when compared to previous years.
- Gradual increases in electrical conductivity and total dissolved solids in BHS5 when considered on a long-term basis.

It is noted that BHAP1 is termed as a control (background) monitoring bore in the 2017 Water Management Plan, as it is "up-gradient" of the quarry.

Table 19: Anions and	cations, annual ave	erages across 2021-2024.

Monitoring Point	Year	Ca (mg/L)	Cl (mg/L)	K (mg/L)	Na (mg/L)	Mg (mg/L)
	2021	56.7	103.3	1.0	49.7	56.3
вн6	2022	51.3	96.5	1.0	47.0	53.0
	2023	53.8	95.0	1.0	41.8	54.3
	2024	51.0	86.8	1.0	46.5	53.0
	2021	30.0	260.0	1.0	110.0	17.0
BHAP1	2022	156.0	486.0	1.0	95.0	5.0
впар і	2023	12.7	111.5	1.0	63.5	6.7
	2024	162.5	450.0	1.0	97.0	5.0
	2021	5.1	80.0	1.0	74.0	7.3
DUAD40	2022	6.0	91.0	1.0	82.0	8.0
BHAP10	2023	4.0	57.0	1.0	60.5	5.2
	2024	4.2	67.5	1.0	72.5	5.3
	2021	10.3	32.5	1.0	15.0	35.0
BHAP5	2022	55.0	51.0	1.0	54.0	35.0
впагэ	2023	9.8	27.0	1.0	12.5	36.0
	2024	51.5	55.0	1.0	56.0	33.5
DUAD/	2021	82.5	74.0	1.0	69.0	33.0
	2022	79.0	79.0	1.0	60.0	32.0
ВНАР6	2023	71.5	81.5	1.0	57.5	30.0
	2024	72.5	61.5	1.0	60.0	30.0

Monitoring Point	Year	Ca (mg/L)	Cl (mg/L)	K (mg/L)	Na (mg/L)	Mg (mg/L)
g. c	2021	12.3	41.3	1.0	16.3	12.4
	2022	8.5	69.3	1.0	22.0	11.0
BHS1	2023	10.6	71.0	1.0	21.5	11.8
	2024	11.0	69.0	1.0	23.0	13.0
	2021	17.7	39.7	1.0	24.3	15.7
	2022	9.3	83.5	1.0	42.0	13.3
BHS2	2023	15.0	78.5	1.0	53.5	16.0
	2024	6.3	57.8	1.0	35.5	10.1
	2021	23.7	180.0	1.0	73.3	33.7
	2022	5.8	150.3	1.0	68.8	14.3
BHS3	2023	8.9	111.5	1.0	56.5	15.2
	2024	8.9	138.0	1.0	68.8	16.8
	2021	47.3	45.3	1.0	33.0	59.3
DUG4	2022	52.3	47.0	1.0	33.5	65.5
BHS4	2023	52.3	44.5	1.0	28.0	62.8
	2024	51.3	50.3	1.0	34.0	64.0
	2021	46.0	69.0	1.0	44.0	56.3
DUCE	2022	53.8	140.8	1.0	74.0	70.3
BHS5	2023	57.0	85.0	1.0	56.0	68.8
	2024	62.8	129.0	1.0	79.0	93.0
	2021	42.0	47.0	1.0	58.7	49.7
DUC4	2022					
BHS6	2023					
	2024					
	2021	46.7	160.0	1.0	71.3	80.7
Dhila Carina	2022	61.0	205.8	1.0	94.3	98.8
Phils Spring	2023	56.5	162.5	1.0	78.8	90.3
	2024	56.5	182.8	1.0	87.0	89.8
	2021	33.3	73.3	1.0	37.3	48.3
Cauthau Cauta	2022	19.8	69.3	1.0	42.5	26.5
Southern Spring	2023	28.5	66.3	1.0	35.3	38.5
	2024	23.3	66.8	1.0	42.0	25.3
	2021	44.3	340.0	1.0	210.0	71.3
Western Course	2022	48.3	246.5	1.0	111.5	72.0
Western Spring	2023	25.5	132.5	1.0	67.8	38.3
	2024	39.3	258.0	1.0	127.8	62.0

Table 20: Physical properties, annual averages across 2021-2024. *Average excluding April 2024 result, as discussed in text.

Monitoring Point	Year	Sulfate (mg/L)	EC (µS/cm)	рН	TDS (mg/L)
	2021	4.0	933.3	7.5	533.3
	2022	4.0	877.5	7.4	472.5
ВН6	2023	4.5	797.5	7.8	636.0
	2024	3.3	798.0	7.5	599.8
	2021	7.5	930.0	6.5	685.0
DUA D4	2022	6.5	470.0	6.7	320.0
BHAP1	2023	21.0	1467.5	6.7	1191.0
	2024	21.5	1352.5	7.0	1088.5
	2021	10.0	465.0	6.8	365.0
DUAD40	2022	6.5	360.0	6.7	465.0
BHAP10	2023	4.0	437.0	7.2	313.3
	2024	6.9	415.3	7.0	316.0
	2021	12.5	405.0	8.5	245.0
BHAP5	2022	9.0	415.0	8.4	285.0
БПАГЭ	2023	6.0	701.3	7.6	412.5
	2024	9.6	703.0	7.6	407.3
	2021	7.5	865.0	7.6	470.0
ВНАР6	2022	7.5	840.0	7.7	470.0
ВПАГО	2023	11.0	849.5	7.7	485.0
	2024	10.1	851.8	7.7	9845 / 493.3*
	2021	4.0	233.3	6.4	166.7
BHS1	2022	3.8	300.0	6.1	230.0
Di i3 i	2023	2.3	274.8	6.4	288.3
	2024	2.0	291.5	6.3	341.8
	2021	8.0	360.0	7.1	186.7
BHS2	2022	9.3	485.0	6.7	252.5
51132	2023	4.3	371.5	6.8	233.5
	2024	3.3	283.8	6.6	193.8
	2021	3.7	840.0	6.8	486.7
BHS3	2022	3.8	485.0	6.5	322.5
D1133	2023	4.5	506.0	6.5	310.5
	2024	3.0	517.8	6.6	314.3
BHS4	2021	5.7	863.3	7.4	436.7
	2022	3.0	862.5	6.6	450.0
	2023	3.0	794.3	7.7	419.0
	2024	3.9	787.0	7.6	437.8
	2021	5.3	863.3	7.3	440.0
BHS5	2022	23.0	972.5	7.5	540.0
	2023	9.7	1049.3	7.8	598.8
	2024	5.5	1207.5	7.6	675.3
BHS6	2021	4.3	860.0	7.4	476.7

Monitoring Point	Year	Sulfate (mg/L)	EC (µS/cm)	рН	TDS (mg/L)
	2022				
	2023				
	2024				
	2021	13.0	1266.7	7.5	696.7
Dhile Cowing	2022	10.3	1275.0	7.4	725.0
Phils Spring	2023	13.0	1325.0	7.8	758.0
	2024	14.0	1230.0	7.7	732.5
	2021	4.7	703.3	8.2	403.3
Cautharn Caring	2022	7.8	605.0	8.0	362.5
Southern Spring	2023	6.0	467.8	7.4	299.0
	2024	3.3	496.5	7.2	322.3
Western Spring	2021	16.7	1733.3	7.7	933.3
	2022	2.0	787.5	7.7	442.5
	2023	11.5	1250.0	8.0	755.3
	2024	1.8	1192.0	7.9	741.3

5.5.3 Spring Flow

The Western Spring was visually assessed for flow monthly throughout the reporting period, with the manual estimation measurement method implemented in late 2021 at the Southern Spring continued monthly throughout 2024.

No flow was observed at the Western Spring during any of the monthly inspections, with the amount of water in the adjacent pond fluctuating slightly with rainfall. Samples were collected from this pond at the Western Spring during the year.

As identified in the Annual Review for the previous reporting periods (2022 and 2023), observations at the Southern Spring were impacted by discharge activities, as the outlet for the discharge was upstream of the Southern Spring monitoring / sampling location. As such it was not possible to obtain accurate estimations of flow for the Southern Spring during the April monitoring event, as discharge activities were underway. No flow was observed at the Southern Spring during any other monthly inspection during the reporting period.

Phil's Spring is fitted with an electronic V-Notch weir monitoring device to continuously monitor flow rates. This device suffered a fault in August 2024 and electronic data was therefore not available after this date. The device was updated with a modern unit in early February 2025. While electronic data was not available, manual measurement estimations were made during the monthly inspections, and the results included in monthly reports. The 2017 Water Management Plan requires monitoring of water level (to be converted to flow) at Phils Spring on an approximately quarterly basis (four times per year). As eight monthly measurements were obtained remotely and three manual measurements were obtained (a total of 11 measurements out of 12 months), the reduced monitoring frequency is considered compliant.

The average mean discharge (L/day) as calculated for each month is presented in Figure 17. Flow rate across the monitoring period fluctuated, however the trend was relatively

consistent with the previous reporting period. Flow rates observed were slightly higher than the previous two reporting periods (Table 21).




Figure 17: Mean discharge (L/day) observed at the Phils Spring monitoring location. Device inactive between 4 June 2021 and 18 August 2021. Manual measurements are presented for October-December 2024. No measurement was obtained in September 2024. The relevant period for this report is highlighted in grey.

Table 21: Mean discharge (L/day) observed at the Phils Spring monitoring location as an annual average.

Name	Annual mean discharge (L/day)
2018	9276
2019	8357
2020	8488
2021	9827
2022	6690
2023	7885
2024	8072

5.5.4 Discharge-trial related monitoring

Monitoring requirements associated with the discharge trial (Condition U1 of the EPL) were included on the EPL following its variation in November 2022. This includes characterisation sampling of the on-site accumulated water prior to commencement of discharge, and monthly sampling during discharge, of both the on-site water and at three off-site locations. During the reporting period, the four-month continuation of the trial (i.e. discharge trial extension) occurred, which commenced on 10 January 2024 and ceased on 9 May 2024. Four characterisation samples and four monthly ambient samples were obtained during this period. Results from these sample are presented in Table 22 and Table 23, below.

Table 22: Results from characterisation sampling of water to be discharged, 2024.

Date	Sample	EC (μS/cm)	рН	Turbidity (NTUs)	TSS (mg/L)	COD (mg/L)	Oil and Grease (mg/L)
2/01/2024	S1	444	7.95	2.6	<5	13	<5
15/02/2024	S1	446	8.08	12.7	13	16	<5
2/04/2024	S1	408	8.11	20.6	18	<10	<5
30/04/2024	S1	480	8.26	11.7	18	<10	<5

Table 23: Results from monthly ambient water quality monitoring during discharge.

Date	Sampling location	EC (μS/cm)	рН	TSS (mg/L)	COD (mg/L)	Oil and Grease (mg/L)
10/01/2024	DCD	449	8.24	12	<10	<5
10/01/2024	JC-US	431	8.03	6	36	<5
10/01/2024	JC-DS	440	8.18	5	24	<5
15/02/2024	DCD	413	8.15	18	29	<5
15/02/2024	JC-US	587	7.98	8	35	<5
15/02/2024	JC-DS	641	8.07	11	36	<5
2/04/2024	DCD	500	8.15	<5	<10	<5
2/04/2024	JC-US	646	7.82	8	29	<5
2/04/2024	JC-DS	652	7.99	7	26	<5
30/04/2024	DCD	464	8.33	6	<10	<5
30/04/2024	JC-US	420	7.72	9	29	<5
30/04/2024	JC-DS	390	7.92	<5	35	<5

5.5.5 Discharge-trial related photo point monitoring

The watercourse south of the Approved Extraction Area was inspected during the reporting period monthly from February to May (i.e. on four separate occasions), with photographs obtained at five locations and compared to a baseline from August 2022. Observations made during this time were consistent that vegetation growth within the channel had increased, with no obvious erosion or scouring since the commencement of discharge. Photographs and specific observations were included in the discharge reports submitted to the EPA as a requirement of the trial.

5.6 Heritage

No artefacts or items of cultural value were recovered throughout 2024, and no areas identified in the current or revised Aboriginal Heritage Management Plan as containing heritage items were disturbed.

5.7 Invasive species

No programs were conducted during the reporting period to manage invasive species. Historically the Quarry has been affected by foxes, deer, pigs, and rabbits. Weed control

is likely to be undertaken in the next reporting period (2026) for invasive vegetation, if considered necessary.

6. Water management

Three active Water Access Licences (**WAL**s) are currently held by the Ardmore Park Quarry. Two licences (30111 and 41848) are directed to the Goulburn Fractured Rock Aquifer, subject to the Water Sharing Plan for the Greater Metropolitan Region Groundwater Sources, with the third WAL permitting water use from Bungonia Creek (25390). A summary of each of these WALs is presented in Table 24.

Table 24: Summary of Water Access Licences (WALs).

WAL	Summary
WAL 30111 - "BHAP6" or "The Production Bore"	BHAP6 is a deep bore located at the centre of the Quarry property. Water from BHAP6 is generally used for dust suppression, amenities, truck washing, on-site concrete production, and rock washing. Although infrastructure was installed to connect the accumulated water covered by WAL 41848 to the rock washing area, use of BHAP6 increased during the reporting period.
WAL 41848 - "The Bubbler"	Water is obtained at a sled mounted pump located in the Old Pit quarry void, drawing from surface and intercepted groundwater water collected in the voids. Water from this point is utilised for sand washing, dust suppression, and rock washing, or discharged off-site when permitted by the EPL. A significant proportion of this water is surface water, with the Old Pit accumulating large volumes of water during heavy rain events.
WAL 25390	No water has been used under this WAL in 2023.

Water use for 2024 is summarised below in Table 25. Water usage from WAL 30111 was relatively stable for approximately two thirds of the reporting period, and then increased after September 2024. Water use was significantly lower than the previous reporting period (approx. 33 ML) and remained well within the permitted entitlements.

Water usage from WAL 41848 was not possible to be accurately tracked during the reporting period, as the WAL covers intercepted groundwater only, while the water discharged from the Old Pit (which was tracked), included both intercepted groundwater and accumulated surface water. The majority of this water was surface water.

As previously reported in the 2022 Annual Review, the raw figures for WAL 41848 "use" as shown in Table 25 slightly exceed the entitlement, as these figures do not differentiate between the high volume of accumulated surface water and infiltrated groundwater. As proposed in the 2022 Annual Review, WaterNSW has been contacted informing them of this issue and seeking their input as to a potential solution. As of the publication of this report, no response has been received.

Table 25: Water entitlements and usage, 2024. Annual values are approximate as meter readings were not taken on the first and last day of the reporting period. *One unit under the water sharing plan is equivalent to an entitlement of one ML. **As discussed above, the raw value for usage does not accurately reflect the amount of groundwater used (as surface water is also included), and as such the percentage of entitlement used is also inaccurate.

	BHAP6 (WAL 30111)				
	First reading	Final reading	Total (m³)		
Date	9/01/2024	9/01/2025			
Reading (m³)	167341	20436.14	20436.14		
	Approx. tota (M	20.44			
	Entitlement	110			
	Approx. entiti 2024	18.6%			

WAL 41848	
Approx. total usage 2024** (ML)	104
Entitlement units* (ML)	100
Approx. entitlement used 2024** (%)	104
Approx. total usage 2024 (ML), assuming 19% groundwater	19.7
Approx. entitlement used 2024 (%), assuming 19% groundwater	19.7%

Meter readings for BHAP6 since February 2018 are presented in Figure 18, which shows the increase of water take towards the end of this reporting period.




Figure 18: Meter readings (m^3) for WAL 30111. The relevant period for this report is highlighted in orange.

6.1 Water year (1 July 2023 - 30 June 2024)

The water year (1 July 2023 - 30 June 2024) is not equivalent to the reporting period of this Annual Review (1 January 2024 - 31 December 2024). The water taken during the water year from WAL 30111 is presented in Table 26, below, and observed to be well within the permitted entitlements.

Table 26: Water entitlements and usage during the previous water year for WAL 30111. Values are approximate as meter readings were not taken on the first and last day of the water year. *One unit under the water sharing plan is equivalent to an entitlement of one ML. **Closest reading to 1 July 2023. ***Closest reading to 30 June 2024.

	ВНА	BHAP6 (WAL 30111)				
	First reading Final reading		Total (m³)			
Date	5/07/2023**	5/07/2023** 11/07/2024***				
Reading (m³)	144513 170243		25730			
	Approx. total usag	25.73				
	Entitleme	110				
	Approx. entitlen	23.4%				

As discussed in the previous section of this report, the groundwater usage from WAL 41848 was not possible to accurately track, as the WAL covers intercepted groundwater only, while the water taken from the Old Pit and used on site and discharged from the Old Pit, included both intercepted groundwater and accumulated surface water. The total amount of water removed from the Old Pit during the water year is presented in Table 27, below.

Table 27: Water entitlements and usage during the previous water year for WAL 41848. *One unit under the water sharing plan is equivalent to an entitlement of one ML. **As discussed above, the raw value for usage does not accurately reflect the amount of groundwater used (as surface water is also included), and as such the percentage of entitlement used is also inaccurate.

	WAL 41848				
	Meter start	Meter end	Total (m³)		
Date	5/07/2023 30/04/2024				
Reading (m³)	141808 270728		128920		
	Approx. total usa	128.92			
	Entitleme	100			
	Approx. entitlement us	129%			
Approx. total usage 202	24.5				
Approx. entitlement use	d 2023-24 Water Year (%),	assuming 19% groundwater	24.5%		

As per the letter sent to Water NSW (referenced in the previous section), approximately 19% of the water accumulated in the Old Pit is predicted to have originated from the Goulburn Fractured Rock Groundwater Source. Considering this fraction, we would assume 24.5 ML of the total amount of water removed from the Old Pit during the water year to be sourced from groundwater, a total of 24.5% of the entitlement.

6.2 2017 Water Management Plan

Activities on Site with regard to water management are to be conducted in accordance with the 2017 Water Management Plan (WMP) prepared by RW Corkery & Co, Pty Ltd (RWC). It is noted that a revised WMP was prepared for submission to the Department, but (as discussed in Table 36) due to the correspondence that no further action would be taken regarding the review and approval of submitted management plans this was not progressed.

6.2.1 Groundwater monitoring requirements

Section 8.4 of the 2017 WMP details the groundwater monitoring required to be undertaken, as presented in Table 28, below.

Table 28: Groundwater	monitorina re	auirements as	presented in t	the 2017 WMP

Analyte / Aquifer	Hard Rock (BHAP1, BHAP5, BHAP6, BHAP10)	Sand (BH1-6)	Spring (Phils, Southern)
Standing Water Level	Quarterly	Quarterly	Quarterly
pH, EC, TDS	Quarterly	Quarterly	Quarterly
Organic Suite	N/A	Quarterly	Quarterly
Cation/Anion Suite	Annual	Annual	Annual
Metals Suite	Annual	Annual	Annual

All groundwater monitoring of the hard rock aquifer bores (BHAP1, BHAP5, BHAP6, BHAP10) was undertaken during the reporting period, as required. The annual monitoring event was conducted in January 2024, with subsequent quarterly monitoring events conducted in April 2024, July 2024, and October 2024. Monitoring of the standing water level (SWL) of each bore was conducted monthly, in excess of the WMP requirements.

Groundwater monitoring of the sand aquifer bore BH6 was undertaken during the reporting period, as required. The annual monitoring event was conducted in January 2024, with subsequent quarterly monitoring events conducted in May 2024 (due to accessibility and safety issues in April, with insufficient light remaining during the sampling event for the sample to be obtained safely), July 2024, and October 2024. Monitoring of the standing water level (SWL) of the bore was conducted monthly, in excess of the WMP requirements. Groundwater monitoring of the sand aquifer bores BH1-BH5 could not be conducted, due to the historical destruction of these bores in accordance with extraction activities. A new series of shallow sand bores (BHS1-BHS6) was installed at the quarry to replace these bores, and monitoring at these locations is conducted in accordance with the requirements of the EPL.

These updated monitoring requirements and locations are presented in a revised Water Management Plan, as discussed above.

All monitoring of the springs (Phils Spring, Southern Spring) was undertaken during the reporting period, as required. The annual monitoring event was conducted in January 2024, with subsequent quarterly monitoring events conducted in April 2024 at Phils

Spring and May 2024 at Southern Spring (due to accessibility and safety issues in April, with insufficient light remaining during the sampling event for the sample to be obtained safely), July 2024, and October 2024. Monitoring of the water level of Phils Spring was determined by the remote, V-notch weir, and converted to monthly flow measurements. Where the remote logger experienced a fault from August 2024 to the end of the reporting period, manual estimate measurements were obtained (excepting in September 2024) as an alternative. Flow measurement observations and estimates were obtained from the Southern Spring monthly, in excess of the WMP requirements.

A summary of all analytes monitored from each of the groundwater bores and springs, and their frequency during the reporting period is presented in Table 15.

Section 8.4.5 of the WMP requires photo points to be established at Phil's Spring and the Southern Spring, with photographs to be taken at least annually. Photographs were taken from these locations at multiple times throughout the reporting period, compliant with this requirement. All photographs are uploaded to a secure, cloud-based storage system with regular back-ups.

6.2.2 Data management protocol

Section 8.8 of the WMP includes a data management protocol, with specifics presented in Table 29.

Table 29: Data Management Protocol presented in Section 8.8 of the 2017 Water Management Plan.

Response for 2024 reporting period **Protocol** The water level data downloaded from the Section 8.4.2.1 of the WMP stated that loggers in the monitoring bores and census automated submersible Pressure and springs will be imported into an electronic Temperature Data Recorders ("loggers") would database or spreadsheet and viewed following be installed in the bores. These loggers have each round of monitoring. This process will since been removed, due to a number of ensure that a progressive record of the data is factors. Standing Water Level (SWL) in each stored and maintained, and the bore is now measured manually each month integrity/quality of the data can be checked on by trained environmental representatives. a regular basis. If a problem with the data is This data is entered into an electronic discovered, for example the corrected water spreadsheet following each monitoring event. level in the data logger does not reasonably which is stored in a secure, cloud-based correspond with the manual measurement system with regular back-ups. taken at the time of downloading, remedial Data is uploaded to the Multiquip website measures can be implemented immediately. If monthly. there is a problem, the worst-case scenario is No data was lost during the reporting period. that water level data may be lost for that period or part of the monitoring period since the last downloading was carried out. In this way, any problem should not be carried through in the medium to long term. Email a copy of the water level data to a 4Pillars representatives assess the water level hydrogeological consultant for assessment data following each monitoring event. All data and keep a backup copy of the water level is stored in a secure, cloud-based system with database in a secure off-site location. regular back-ups, as well as being uploaded to the Multiquip website monthly. Develop and maintain a water usage record for A water usage record has been developed and the Quarry. This database can be part of the is maintained monthly, following each site electronic water level monitoring database. inspection. This record is stored in a secure, cloud-based system with regular back-ups.

Protocol	Response for 2024 reporting period
The water level data downloaded from the loggers in the monitoring bores and census springs will be imported into an electronic database or spreadsheet and viewed following each round of monitoring. This process will ensure that a progressive record of the data is stored and maintained, and the integrity/quality of the data can be checked on a regular basis. If a problem with the data is discovered, for example the corrected water level in the data logger does not reasonably correspond with the manual measurement taken at the time of downloading, remedial measures can be implemented immediately. If there is a problem, the worst-case scenario is that water level data may be lost for that period or part of the monitoring period since the last downloading was carried out. In this way, any problem should not be carried through in the medium to long term.	Section 8.4.2.1 of the WMP stated that automated submersible Pressure and Temperature Data Recorders ("loggers") would be installed in the bores. These loggers have since been removed, due to a number of factors. Standing Water Level (SWL) in each bore is now measured manually each month by trained environmental representatives. This data is entered into an electronic spreadsheet following each monitoring event, which is stored in a secure, cloud-based system with regular back-ups. Data is uploaded to the Multiquip website monthly. No data was lost during the reporting period.
Develop and maintain an electronic water quality database or spreadsheet. This database can also be part of the electronic water level monitoring database. A suitable database and progressive charting will be developed.	An electronic water quality spreadsheet has been developed and is maintained quarterly, following each sampling event.
Develop and maintain an electronic spring flow database or spreadsheet. This database can also be part of the electronic water level and water quality monitoring database. A suitable database and progressive charting will be developed.	An electronic spring flow spreadsheet has been developed and is maintained monthly, following each site inspection. Electronic remote data from the V-notch weir installed at Phils Spring is used to populate the spreadsheet, along with manual estimate measurements from the Southern Spring and Western Spring. This data is presented in the monthly Environmental Monitoring Reports which are uploaded to the Multiquip website.
Develop and maintain an electronic rainfall database or spreadsheet. This database can also be part of the electronic water level monitoring database.	An electronic rainfall spreadsheet has been developed and is maintained monthly. Data used to populate the spreadsheet is obtained from on-site monitoring device "PM10_W".

6.2.3 Triggers, Actions, Responses and Reporting

Two triggers for Water Level or Water Quality in Table 6 of the WMP were observed in the reporting period, discussed below.

Elevated TDS - BHAP6

The 10/04/2024 sample obtained from BHAP6 returned an elevated level of TDS (37,900 mg/L) that exceeded the trigger value of >2,000 mg/L. The exceedance was attributed to a high level of silt collected within the sample due to recent pumping of the bore for operational use. As this was a one-off exceedance with likely causes, BHAP6 was not resampled within 2 weeks, and the following sampling event in July showed a return to normal TDS value which is below the trigger value. Further actions taken were to: continue to monitor, and avoid sampling BHAP6 following recent pumping events

Reduced pH – BHS1

The 11/07/2024 sample obtained from BHS1 returned a reduced pH level (5.92) that was slightly beneath the trigger value of <6.0. As this was a one-off minor exceedance, BHS1 was not resampled within two weeks. Further actions taken were to resample in October to continue to monitor the pH level in BHS1. The following sample obtained in October showed a return to a normal pH value of 6.2 value which was compliant with the trigger value.

No flow was observed in the Southern Spring during the reporting year, except during discharge activities. The 2017 WMP did not present a baseline flow measurement for the Southern Spring. It is noted that the Larry Cook and Associates Pty Ltd 2008 Groundwater Impact Assessment prepared by for the project stated that no flow was noted in the Southern Spring during its inspection in November 2004, and that the paucity of any significant flow and the setting indicated that this system from which the spring generates water was not likely to be significant. Discharge of water into the watercourse of the Southern Spring was carried out during the reporting period in accordance with the EPL-approved discharge trial and extension.

During the reporting period, there were five months (out of eight) in which the automated logger at Phils Spring presented flow values of <0.1L/s. Of the three supplementary manual estimate measurements taken, only one month (out of three measurements) returned a flow value of <0.1L/s. In accordance with the Table 6 triggers, monitoring and assessment of the flow rate was continued, and graphs prepared. A comparison of the flow rate with rainfall data was also undertaken, which suggested a strong visual correlation between the data especially from April 2024 onwards. Considering the repairs undertaken to all on-site remote monitoring devices in early 2025, an assessment of this trend is worth revisiting once further data is obtained.

Available data since January 2018 from the automated logger has been reviewed and is presented in Table 30, below, taking into account supplementary manual measurements for Oct-Dec 2024 as discussed above. When compared to this long-term data, the observations for 2024 seem reasonably consistent, although generally lower than the assumptions presented in the WMP. It is noted that the minimum flow values recorded during the reporting period are lower than previous years, although the average flow values are slightly higher than the previous two reporting periods.

Table 30: Automated logger data for Phils Spring, as well as supplementary manual measurements for Oct-Dec 2024 due to a device fault.

Year	Minimum flow (L/s)	Maximum flow (L/s)	Average flow (L/s)	# months > 0.1 L/s
2018	0.09	0.13	0.11	10
2019	0.08	0.11	0.10	7
2020	0.07	0.15	0.10	5
2021	0.10	0.21	0.11	6
2022	0.02	0.27	0.08	3
2023	0.02	0.18	0.09	5
2024	0.01	2.84	0.10	5

No compensatory water supply or other mitigation/contingency plans was offered, needed or implemented during the reporting period. No complaints regarding water on

surrounding properties (reduction or otherwise) were received during the reporting period.

6.2.4 General Reporting Protocol

During the reporting period, reporting was undertaken in general accordance with the general reporting protocol presented in Section 8.9 of the WMP, with some minor variations. Specifics have been provided in Table 31.

Table 31: General Reporting Protocol presented in Section 8.9 of the 2017 Water Management Plan.

Protocol	Response for 2024 reporting period
All water level data, groundwater quality monitoring results and spring flow will be recorded, collated and duly reported in-house on at least a six-monthly basis for the first 12 months, henceforth on an annual basis. The data will be reviewed by a consulting hydrogeologist. The aim is to assess any changes in water levels, groundwater chemistry or spring flow and identify reasons for the changes if they occur. The monitoring schedule will be reviewed annually and changed if deemed appropriate by the consultant.	All data is recorded, collated, and reported monthly (SWL, spring flow), quarterly (water quality - some analytes), and annually (water quality - additional analytes). The data is assessed by 4Pillars representatives upon receipt. The monitoring schedule has changed since the preparation of the 2017 WMP, considering the destruction of a number of the listed bores in accordance with extractive activities, however, the remaining bores continue to be monitored in accordance with the 2017 WMP.
A complete set of audit results from the monitoring program will be formally reported to the Senior Hydrogeologist of the NSW Office of Water (DPI-Water) on an annual basis.	The required data (December 2024 EMR + 2023 Annual Review) was provided to the NSW Department of Climate Change, Energy, the Environment and Water (DCCEEW) Water Group addressed to the Senior Hydrogeologist of the NSW Office of Water on 20 December 2024.
The report will provide a summary of the water extraction records for the Quarry and monitoring results. The report will include a figure showing the locations of the monitoring sites, and a set of hydrographs with rainfall correlations. The report will be sent in hard copy to the Senior Hydrogeologist of DPI-Water. The raw	All data obtained during the reporting period was presented in the monthly Environmental Monitoring Reports which are uploaded to the Multiquip website, along with a figure showing the locations of the monitoring sites. Rainfall data is presented in the Annual Review. The equivalent reports (December 2024 EMR + 2023 Annual Review) were provided to the
water level data can be appended to the report in electronic form. The complete report will also be submitted in electronic format to DPI-Water and to the Quarry Manager.	NSW DCCEEW Water Group addressed to the Senior Hydrogeologist of the NSW Office of Water in electronic format as per current practicalities, rather than as a hard copy. This is an appropriate equivalent and not considered to be a non-compliance. No response to the contrary was received. The Quarry Manager is provided all prepared Environmental Monitoring Reports in electronic format.

6.2.5 Surface water quality monitoring and stream health monitoring

Surface Water Monitoring is detailed in Section 4 of the WMP.

Section 4.1 of the WMP (Water Quality Monitoring - CP3) requires the collection and laboratory analysis of water samples from dams CP3 (Dam 7) and Dam 8, if at any time the settling volume of Dam CP3 is compromised, and off-site disposal is required. Dam CP3 is still present, however due to the quarrying activities, the catchment feeding into this dam has been reduced, and little water accumulates in it. As such, there is now only a small dam still present in this location. At no time during the reporting period was the settling volume of this dam compromised, and as such the sampling and analysis requirements were not required to be implemented.

Section 4.2 of the WMP (Stream Health Monitoring (Receiving Water) requires the Quarry Manager to inspect the length of the watercourse south of Dam CP3 every six months, obtain a series of five photographs, and determine whether "any significant signs of accelerated erosion" are identified.

As part of the monitoring associated with the discharge trial and extension undertaken on the site, this watercourse was inspected during the reporting period monthly from February to May 2024 (i.e. on four separate occasions), with photographs obtained at five locations and compared to a baseline from August 2022. Observations made during this time were consistent that vegetation growth within the channel had increased, with no obvious erosion or scouring since the commencement of discharge. In light of this outcome with the elevated volume of water travelling along the watercourse in association with the discharge trial, it is considered unlikely that significant signs of accelerated erosion would be associated with general quarrying activities. The Quarry Manager also regularly inspects this watercourse, and observations made correlate with those made during the discharge inspections.

This monitoring is considered compliant with the requirements of Section 4.2. of the WMP.

Section 4.3 of the WMP (Weather Monitoring) references the presence on site of an automatic weather station which measures daily rainfall, with results continuously logged and kept on file. This section details that untreated site discharges are only permissible after a rainfall event that exceeds the 95th percentile, 5-day rainfall depth (41mm). Weather monitoring was carried out as per this section. All discharges from the site were carried out in accordance with the EPL-approved discharge trial and extension, permitted by Condition 12 of Schedule 3 of the Project Approval, which states that "the Proponent shall not discharge any water from the quarry or its associated operations except in accordance with an EPL."

As such, compliance with Section 4.3 was maintained throughout the reporting period.

6.2.6 Site auditing

Section 6 of the WMP requires that once per year, a hydrological consultant, Certified Professional in Erosion and Sediment Control (CPESC) or other appropriately qualified professional will be commissioned to inspect the site and prepare a report. The WMP does not detail submission/publication requirements for this report, and it is as such considered an internal requirement.

As mentioned above, 4Pillars attends the site each month to undertake monitoring and sampling in accordance with the requirements of the Project Approval and EPL. While a standalone annual report was not prepared as required by Section 6, the majority of the

required contents of this report were included in various reports including the Annual Reviews and monthly Environmental Monitoring Reports, as shown in Table 32, below. Other items were discussed with Site personnel, as required.

Table 32: Requirements of annual report to be prepared in accordance with Section 6 of the WMP.

Results of an inspection of the weather station and its records. Results of an inspection of the pumping records. Results of an inspection of the untreated discharge records, and comparison with rainfall data. Results of an inspection of the untreated discharge records, and comparison with rainfall data. Results of an inspection of the volumes of water collected in Dam 8 and RE2 after rainfall events (for model calibration - Section 3.1). Results of an inspection of the condition of all ponds and drainage structures. Results of an inspection of the condition of all ponds and drainage structures. Results of an inspection of the condition of all ponds and drainage structures. Results of an inspection of the condition of all ponds and drainage structures. Results of an inspection of the condition of all ponds and drainage structures. Results of an inspection of the condition of all ponds and drainage structures. Results of an inspection of the condition of all ponds and drainage structures are observed to require maintenance, this is raised following each inspection, with action taken. Results of an inspection of the condition of any rehabilitated areas. Results of an inspection of the condition of any rehabilitated areas. Results of an inspection of the condition of any rehabilitated areas. Results of an inspection of the condition of any rehabilitated areas. Results of an inspection of the condition of any rehabilitation are required, not one formal inspections are required, provided and representation of provided and record are representation. Results of an inspection of the condition of any rehabilita	Contents of report	Included in reports / Internally assessed
and its records. Weekly, with data downloaded monthly, Records are held in an electronic database. Relevant data is presented in the Annual Review. Meter readings from BHAP6 are taken monthly by 4Pillars during site inspections, with supplementary readings obtained by the Quarry Manager or site personnel on an ad hoc basis or as required. These readings are entered into an electronic database, with use data submitted to WaterNSW via the WMS Portal. These records are also presented in the Annual Review. Meter readings from the discharge activities are taken at the start and finish of each day of discharge by the Quarry Manager or their delegate. These meter readings are reviewed during the presentation of discharge reports as required by the EPA. Results of an inspection of the untreated discharge records, and comparison with rainfall data. Results of an inspection of the volumes of water collected in Dam 8 and RE2 after rainfall yeento (for model calibration - Section 3.1). Results of an inspection of the condition of all ponds and drainage structures. M/A, the WMP states that subject to rainfall, this will only be required for two years. This time period has since passed. Inspection of ponds and drainage structures for environmental purposes occur regularly, particularly after rain, However, if no actions are required, records are not kept of each of these inspections. Daily inspections are undertaken by the Site Supervisor which assess these structures and dams from a safety perspective. If any of these structures are observed to require maintenance, this is raised following each inspection, with action taken. Only one location has been rehabilitated, which is a bund constructed along the southern boundary of the Site. This bund is fully re-vegetated, and no formal inspections are required, though it is observed on a regular basis by the Site Supervisor and Quarry Manager. All other areas which will require rehabilitation are still in use, and as such no rehabilitation has been undertaken.	Contents of report	Included in reports / Internally assessed
Results of an inspection of the pumping records. Results of an inspection of the pumping records. Results of an inspection of the pumping records. Meter readings from BHAP6 are taken monthly by 4Pillars during site inspections, with supplementary readings obtained by the Quarry Manger or site personnel on an ad hoc basis or as required. These readings are entered into an electronic database, with use data submitted to WaterNSW via the iWAS Portal. These records are also presented in the Annual Review. Meter readings from the discharge activities are taken at the start and finish of each day of discharge by the Quarry Manager or their delegate. These meter readings are reviewed during the presentation of discharge reports as required by the EPA. N/A, this kind of discharge mentioned in the WMP did not occur during the reporting period. Results of an inspection of the volumes of water collected in Dam 8 and RE2 after rainfall events (for model calibration - Section 3.1). Results of an inspection of the condition of all ponds and drainage structures. Results of an inspection of the condition of all ponds and drainage structures. Results of an inspection of the condition of all ponds and drainage structures. Results of an inspection of the condition of all ponds and drainage structures. Results of an inspection of the condition of all ponds and drainage structures. Results of an inspection of the condition of all ponds and drainage structures. Results of an inspection of the condition of all ponds and drainage structures. Results of an inspection of the condition of all ponds and drainage structures. Results of an inspection of the condition of all ponds and drainage structures. Results of an inspection of the condition of all ponds and drainage structures are observed to require maintenance, this is raised following each inspection, with action taken. Results of an inspection of the condition of any repaired ponds and		
Results of an inspection of the pumping records. Results of an inspection of the pumping records. Meter readings from BHAP6 are taken monthly by 4Pillars during site inspections, with supplementary readings obtained by the Quarry Manger or site personnel on an ad hoc basis or as required. These readings are entered into an electronic database, with use data submitted to WaterNSW via the iWAS Portal. These records are also presented in the Annual Review. Meter readings from the discharge activities are taken at the start and finish of each day of discharge by the Quarry Manager or their delegate. These meter readings are reviewed during the presentation of discharge reports as required by the EPPA. Results of an inspection of the untreated discharge records, and comparison with rainfall data. Results of an inspection of the volumes of water collected in Dam 8 and RE2 after rainfall events (for model calibration – Section 3.1). Results of an inspection of the condition of all ponds and drainage structures. Results of an inspection of the condition of all ponds and drainage structures. Results of an inspection of the condition of all ponds and drainage structures. Results of an inspection of the condition of all ponds and drainage structures. Results of an inspection of the condition of all ponds and drainage structures. Results of an inspection of the condition of all ponds and drainage structures. Results of an inspection of the condition of all ponds and drainage structures. Results of an inspection of the condition of all ponds and drainage structures. Results of an inspection of the condition of all ponds and drainage structures. Results of an inspection of the condition of all ponds and drainage structures and dams from a safety perspective. If any of these structures are observed to require maintenance, this is raised following each inspection, with action taken. Results of an inspection of the condition of any rehabilitated, and no formal inspections are required, though it is observed on a	and its records.	
Results of an inspection of the pumping records. Meter readings from BHAP6 are taken monthly by 4Pillars during site inspections, with supplementary readings obtained by the Quarry Manger or site personnel on an ad hoc basis or as required. These readings are entered into an electronic database, with use data submitted to WaterNSW via the itWAS Portal. These records are also presented in the Annual Review. Meter readings from the discharge activities are taken at the start and finish of each day of discharge by the Quarry Manager or their delegate. These meter readings are reviewed during the presentation of discharge reports as required by the EPA. N/A, this kind of discharge mentioned in the WMP did not occur during the reporting period. Results of an inspection of the volumes of water collected in Dam 8 and RE2 after rainfall events (for model calibration – Section 3.1). Results of an inspection of the condition of all ponds and drainage structures. N/A, the WMP states that subject to rainfall, this will only be required for two years. This time period has since passed. Inspection of ponds and drainage structures for environmental purposes occur regularly, particularly after rain, However, if no actions are required, records are not kept of each of these inspections. Daily inspections are undertaken by the Site Supervisor which assess these structures and dams from a safety perspective. If any of these structures are observed to require maintenance, this is raised following each inspection, with action taken. Only one location has been rehabilitated, which is a bund constructed along the southern boundary of the Site. This bund is fully re-vegetated, and no formal inspections are required, though it is observed on a regular basis by the Site Supervisor and Quarry Manager. All other areas which will require rehabilitation are still in use, and as such no rehabilitation has been undertaken.		
Results of an inspection of the pumping records. Meter readings from BHAP6 are taken monthly by 4Pillars during site inspections, with supplementary readings obtained by the Quarry Manger or site personnel on an ad hoc basis or as required. These readings are entered into an electronic database, with use data submitted to WaterNSW via the iWAS Portal. These records are also presented in the Annual Review. Meter readings from the discharge activities are taken at the start and finish of each day of discharge spy the Quarry Manager or their delegate. These meter readings are reviewed during the presentation of discharge reports as required by the EPA. Results of an inspection of the untreated discharge records, and comparison with rainfall data. Results of an inspection of the volumes of water collected in Dam 8 and RE2 after rainfall events (for model calibration - Section 3.1). Results of an inspection of the condition of all ponds and drainage structures. Results of an inspection of the condition of all ponds and drainage structures. Results of an inspection of the condition of all ponds and drainage structures. Results of an inspection of the condition of all ponds and drainage structures. Results of an inspection of the condition of all ponds and drainage structures. Results of an inspection of the condition of all ponds and drainage structures and dams from a safety perspective. If any of these structures are observed to require maintenance, this is raised following each inspections are undertaken by the Site Supervisor which assess these structures and dams from a safety perspective. If any of these structures are observed to require maintenance, this is raised following each inspection, with action taken. Results of an inspection of the condition of any rehabilitated, which is a bund constructed along the southern boundary of the Site. This bund is fully re-vegetated, and no formal inspections are required, though it is observed on a regular basis by the Site Supervisor and Quarry Manager. All		·
by 4Pillars during site inspections, with supplementary readings obtained by the Cuarry Manger or site personnel on an ad hoc basis or as required. These readings are entered into an electronic database, with use data submitted to WaterNSW via the iWAS Portal. These records are also presented in the Annual Review. Meter readings from the discharge activities are taken at the start and finish of each day of discharge by the Quarry Manager or their delegate. These meter readings are reviewed during the presentation of discharge reports as required by the EPA. Results of an inspection of the untreated discharge records, and comparison with rainfall data. Results of an inspection of the volumes of water collected in Dam 8 and RE2 after rainfall events (for model calibration – Section 3.1). Results of an inspection of the condition of all ponds and drainage structures. N/A, the WMP states that subject to rainfall, this will only be required for two years. This time period has since passed. Inspection of ponds and drainage structures for environmental purposes occur regularly, particularly after rain, However, if no actions are required, records are not kept of each of these inspections. Daily inspections are undertaken by the Site Supervisor which assess these structures and dams from a safety perspective. If any of these structures are observed to require maintenance, this is raised following each inspection, with action taken. Only one location has been rehabilitated, which is a bund constructed along the southern boundary of the Site. This bund is fully re-vegetated, and no formal inspection are required, though it is observed on a regular basis by the Site Supervisor and Quarry Manager. All other areas which will require rehabilitation are still in use, and as such no rehabilitation has been undertaken.	Results of an inspection of the numbing	
supplementary readings obtained by the Quarry Manger or site personnel on an ad hoc basis or as required. These readings are entered into an electronic database, with use data submitted to WaterNSW via the iWAS Portal. These records are also presented in the Annual Review. Meter readings from the discharge activities are taken at the start and finish of each day of discharge by the Quarry Manager or their delegate. These meter readings are reviewed during the presentation of discharge reports as required by the EPA. Results of an inspection of the untreated discharge records, and comparison with rainfall data. Results of an inspection of the volumes of water collected in Dam 8 and RE2 after rainfall events (for model calibration - Section 3.1). Results of an inspection of the condition of all ponds and drainage structures. Inspection of ponds and drainage structures for environmental purposes occur regularly, particularly after rain, However, if no actions are required, records are not kept of each of these inspections. Daily inspections are undertaken by the Site Supervisor which assess these structures and dams from a safety perspective. If any of these structures are observed to require maintenance, this is raised following each inspection, with action taken. Only one location has been rehabilitated, which is a bund constructed along the southern boundary of the Site. This bund is fully re-vegetated, and no formal inspections are required, though it is observed on a regular basis by the Site Supervisor and Quarry Manager. All other areas which will require rehabilitation are still in use, and as such no rehabilitation has been undertaken. Identification of any areas of disturbed soil that		
Quarry Manger or site personnel on an ad hoc basis or as required. These readings are entered into an electronic database, with use data submitted to WaterNSW via the iWAS Portal. These records are also presented in the Annual Review. Meter readings from the discharge activities are taken at the start and finish of each day of discharge by the Quarry Manager or their delegate. These meter readings are reviewed during the presentation of discharge reports as required by the EPA. Results of an inspection of the untreated discharge records, and comparison with rainfall data. Results of an inspection of the volumes of water collected in Dam 8 and RE2 after rainfall events (for model calibration - Section 3.1). Results of an inspection of the condition of all ponds and drainage structures. N/A, the WMP states that subject to rainfall, this will only be required for two years. This time period has since passed. Inspection of ponds and drainage structures for environmental purposes occur regularly, particularly after rain, However, if no actions are required, records are not kept of each of these inspections. Daily inspections are undertaken by the Site Supervisor which assess these structures and dams from a safety perspective. If any of these structures are observed to require maintenance, this is raised following each inspection, with action taken. Only one location has been rehabilitated, which is a bund constructed along the southern boundary of the Site. This bund is fully re-vegetated, and no formal inspections are required, though it is observed on a regular basis by the Site Supervisor and Quarry Manager. All other areas which will require rehabilitation are still in use, and as such no rehabilitation has been undertaken.	records.	
basis or as required. These readings are entered into an electronic database, with use data submitted to WaterNSW via the iWAS Portal. These records are also presented in the Annual Review. Meter readings from the discharge activities are taken at the start and finish of each day of discharge by the Quarry Manager or their delegate. These meter readings are reviewed during the presentation of discharge reports as required by the EPA. Results of an inspection of the untreated discharge records, and comparison with rainfall data. Results of an inspection of the volumes of water collected in Dam 8 and RE2 after rainfall events (for model calibration - Section 3.1). Results of an inspection of the condition of all ponds and drainage structures. Results of an inspection of the condition of all ponds and drainage structures. Results of an inspection of the condition of all ponds and drainage structures. Dally inspections are undertaken by the Site Supervisor which assess these structures and dams from a safety perspective. If any of these structures are observed to require maintenance, this is raised following each inspection, with action taken. Results of an inspection of the condition of any rehabilitated areas. Only one location has been rehabilitated, which is a bund constructed along the southern boundary of the Site. This bund is fully re-vegetated, and no formal inspections are required, though it is observed on a regular basis by the Site Supervisor and Quarry Manager. All other areas which will require rehabilitation are still in use, and as such no rehabilitation has been undertaken. As above, no other areas of disturbed soil are		
entered into an electronic database, with use data submitted to WaterNSW via the iWAS Portal. These records are also presented in the Annual Review. Meter readings from the discharge activities are taken at the start and finish of each day of discharge by the Cuarry Manager or their delegate. These meter readings are reviewed during the presentation of discharge reports as required by the EPA. Results of an inspection of the untreated discharge records, and comparison with rainfall data. Results of an inspection of the volumes of water collected in Dam 8 and RE2 after rainfall events (for model calibration - Section 3.1). Results of an inspection of the condition of all ponds and drainage structures. Besults of an inspection of the condition of all ponds and drainage structures. Daily inspections are undertaken by the Site Supervisor which assess these structures and dams from a safety perspective. If any of these structures are observed to require maintenance, this is raised following each inspection, with action taken. Results of an inspection of the condition of any rehabilitated areas. Results of an inspection of the condition of any rehabilitated areas. Results of an inspection of the condition of any rehabilitated areas. Results of an inspection of the condition of any rehabilitated areas. Results of an inspection of the condition of any rehabilitated areas. Results of an inspection of the condition of any rehabilitated areas. Results of an inspection of the condition of any rehabilitated areas. Results of an inspection of the condition of any rehabilitated areas. Results of an inspection of the condition of any rehabilitated areas. Results of an inspection of the condition of any rehabilitated areas. Results of an inspection of the condition of any rehabilitated areas. Results of an inspection of the condition of any rehabilitated areas. Results of an inspection of the condition of any rehabilitation are still in use, and as such no rehabilitation are still in use, and as such no rehab		,
data submitted to WaterNSW via the iWAS Portal. These records are also presented in the Annual Review. Meter readings from the discharge activities are taken at the start and finish of each day of discharge by the Quarry Manager or their delegate. These meter readings are reviewed during the presentation of discharge reports as required by the EPA. N/A, this kind of discharge mentioned in the WMP did not occur during the reporting period. N/A, the WMP states that subject to rainfall, this will only be required for two years. This time period has since passed. Inspection of ponds and drainage structures for environmental purposes occur regularly, particularly after rain, However, if no actions are required, records are not kept of each of these inspections. Daily inspections are undertaken by the Site Supervisor which assess these structures and dams from a safety perspective. If any of these structures are observed to require maintenance, this is raised following each inspection, with action taken. Results of an inspection of the condition of any rehabilitated areas. Results of an inspection of the condition of any rehabilitated areas. Results of an inspection of the condition of any rehabilitated areas. All other areas which will require rehabilitation are still in use, and as such no rehabilitation has been undertaken. As above, no other areas of disturbed soil are		
Portal. These records are also presented in the Annual Review. Meter readings from the discharge activities are taken at the start and finish of each day of discharge by the Quarry Manager or their delegate. These meter readings are reviewed during the presentation of discharge reports as required by the EPA. Results of an inspection of the untreated discharge records, and comparison with rainfall data. Results of an inspection of the volumes of water collected in Dam 8 and RE2 after rainfall events (for model calibration – Section 3.1). Results of an inspection of the condition of all ponds and drainage structures. N/A, the WMP states that subject to rainfall, this will only be required for two years. This time period has since passed. Inspection of ponds and drainage structures for environmental purposes occur regularly, particularly after rain, However, if no actions are required, records are not kept of each of these inspections. Daily inspections are undertaken by the Site Supervisor which assess these structures and dams from a safety perspective. If any of these structures are observed to require maintenance, this is raised following each inspection, with action taken. Results of an inspection of the condition of any rehabilitated areas. Only one location has been rehabilitated, which is a bund constructed along the southern boundary of the Site. This bund is fully re-vegetated, and no formal inspections are required, though it is observed on a regular basis by the Site Supervisor and Quarry Manager. All other areas which will require rehabilitation has been undertaken. Identification of any areas of disturbed soil that		
Annual Review. Meter readings from the discharge activities are taken at the start and finish of each day of discharge by the Quarry Manager or their delegate. These meter readings are reviewed during the presentation of discharge reports as required by the EPA. Results of an inspection of the untreated discharge records, and comparison with rainfall data. Results of an inspection of the volumes of water collected in Dam 8 and RE2 after rainfall events (for model calibration – Section 3.1). Results of an inspection of the condition of all ponds and drainage structures. Results of an inspection of the condition of all ponds and drainage structures. Results of an inspection of the condition of all ponds and drainage structures. Daily inspections are undertaken by the Site Supervisor which assess these structures and dams from a safety perspective. If any of these structures are observed to require maintenance, this is raised following each inspection, with action taken. Only one location has been rehabilitated, which is a bund constructed along the southern boundary of the Site. This bund is fully re-vegetated, and no formal inspections are required, though it is observed on a regular basis by the Site Supervisor and Quarry Manager. All other areas which will require rehabilitation are still in use, and as such no rehabilitation has been undertaken. Identification of any areas of disturbed soil that As above, no other areas of disturbed soil are		
Meter readings from the discharge activities are taken at the start and finish of each day of discharge by the Quarry Manager or their delegate. These meter readings are reviewed during the presentation of discharge reports as required by the EPA. Results of an inspection of the untreated discharge records, and comparison with rainfall data. Results of an inspection of the volumes of water collected in Dam 8 and RE2 after rainfall events (for model calibration – Section 3.1). Results of an inspection of the condition of all ponds and drainage structures. Results of an inspection of the condition of all ponds and drainage structures. Results of an inspection of the condition of all particularly after rain, However, if no actions are required, records are not kept of each of these inspections. Daily inspections are undertaken by the Site Supervisor which assess these structures and dams from a safety perspective. If any of these structures are observed to require maintenance, this is raised following each inspection, with action taken. Only one location has been rehabilitated, which is a bund constructed along the southern boundary of the Site. This bund is fully re-vegetated, and no formal inspections are required, though it is observed on a regular basis by the Site Supervisor and Quarry Manager. All other areas which will require rehabilitation are still in use, and as such no rehabilitation has been undertaken. Identification of any areas of disturbed soil that		
are taken at the start and finish of each day of discharge by the Quarry Manager or their delegate. These meter readings are reviewed during the presentation of discharge reports as required by the EPA. Results of an inspection of the untreated discharge records, and comparison with rainfall data. Results of an inspection of the volumes of water collected in Dam 8 and RE2 after rainfall events (for model calibration – Section 3.1). Results of an inspection of the condition of all ponds and drainage structures. Inspection of ponds and drainage structures for environmental purposes occur regularly, particularly after rain, However, if no actions are required, records are not kept of each of these inspections. Daily inspections are undertaken by the Site Supervisor which assess these structures and dams from a safety perspective. If any of these structures are observed to require maintenance, this is raised following each inspection, with action taken. Results of an inspection of the condition of any rehabilitated areas. Only one location has been rehabilitated, which is a bund constructed along the southern boundary of the Site. This bund is fully re-vegetated, and no formal inspections are required, though it is observed on a regular basis by the Site Supervisor and Quarry Manager. All other areas which will require rehabilitation are still in use, and as such no rehabilitation has been undertaken. Identification of any areas of disturbed soil that		
discharge by the Quarry Manager or their delegate. These meter readings are reviewed during the presentation of discharge reports as required by the EPA. Results of an inspection of the untreated discharge records, and comparison with rainfall data. Results of an inspection of the volumes of water collected in Dam 8 and RE2 after rainfall events (for model calibration - Section 3.1). Results of an inspection of the condition of all ponds and drainage structures. Results of an inspection of the condition of all ponds and drainage structures. Results of an inspection of the condition of all ponds and drainage structures. Results of an inspection of the condition of all ponds and drainage structures for environmental purposes occur regularly, particularly after rain, However, if no actions are required, records are not kept of each of these inspections. Daily inspections are undertaken by the Site Supervisor which assess these structures and dams from a safety perspective. If any of these structures are observed to require maintenance, this is raised following each inspection, with action taken. Only one location has been rehabilitated, which is a bund constructed along the southern boundary of the Site. This bund is fully re-vegetated, and no formal inspections are required, though it is observed on a regular basis by the Site Supervisor and Quarry Manager. All other areas which will require rehabilitation are still in use, and as such no rehabilitation has been undertaken. Identification of any areas of disturbed soil that		
delegate. These meter readings are reviewed during the presentation of discharge reports as required by the EPA. Results of an inspection of the untreated discharge records, and comparison with rainfall data. Results of an inspection of the volumes of water collected in Dam 8 and RE2 after rainfall events (for model calibration – Section 3.1). Results of an inspection of the condition of all ponds and drainage structures. Results of an inspection of the condition of all ponds and drainage structures. Inspection of ponds and drainage structures for environmental purposes occur regularly, particularly after rain, However, if no actions are required, records are not kept of each of these inspections. Daily inspections are undertaken by the Site Supervisor which assess these structures and dams from a safety perspective. If any of these structures are observed to require maintenance, this is raised following each inspection, with action taken. Results of an inspection of the condition of any rehabilitated areas. Only one location has been rehabilitated, which is a bund constructed along the southern boundary of the Site. This bund is fully re-vegetated, and no formal inspections are required, though it is observed on a regular basis by the Site Supervisor and Quarry Manager. All other areas which will require rehabilitation are still in use, and as such no rehabilitation has been undertaken. Identification of any areas of disturbed soil are		
Results of an inspection of the untreated discharge records, and comparison with rainfall data. Results of an inspection of the volumes of water collected in Dam 8 and RE2 after rainfall events (for model calibration – Section 3.1). Results of an inspection of the condition of all ponds and drainage structures. Results of an inspection of the condition of all ponds and drainage structures. Results of an inspection of the condition of all ponds and drainage structures. Results of an inspection of the condition of all ponds and drainage structures. Results of an inspection of the condition of all ponds and drainage structures. Results of an inspection of the condition of all ponds and drainage structures. Daily inspections are undertaken by the Site Supervisor which assess these structures and dams from a safety perspective. If any of these structures are observed to require maintenance, this is raised following each inspection, with action taken. Results of an inspection of the condition of any rehabilitated areas. Only one location has been rehabilitated, which is a bund constructed along the southern boundary of the Site. This bund is fully re-vegetated, and no formal inspections are required, though it is observed on a regular basis by the Site Supervisor and Quarry Manager. All other areas which will require rehabilitation are still in use, and as such no rehabilitation has been undertaken. Identification of any areas of disturbed soil that		, ,
Results of an inspection of the untreated discharge records, and comparison with rainfall data. Results of an inspection of the volumes of water collected in Dam 8 and RE2 after rainfall events (for model calibration - Section 3.1). Results of an inspection of the condition of all ponds and drainage structures. Results of an inspection of the condition of all ponds and drainage structures. Inspection of ponds and drainage structures for environmental purposes occur regularly, particularly after rain, However, if no actions are required, records are not kept of each of these inspections. Daily inspections are undertaken by the Site Supervisor which assess these structures and dams from a safety perspective. If any of these structures are observed to require maintenance, this is raised following each inspection, with action taken. Results of an inspection of the condition of any rehabilitated areas. Only one location has been rehabilitated, which is a bund constructed along the southern boundary of the Site. This bund is fully re-vegetated, and no formal inspections are required, though it is observed on a regular basis by the Site Supervisor and Quarry Manager. All other areas which will require rehabilitation are still in use, and as such no rehabilitation has been undertaken. Identification of any areas of disturbed soil that As above, no other areas of disturbed soil are		during the presentation of discharge reports
discharge records, and comparison with rainfall data. Results of an inspection of the volumes of water collected in Dam 8 and RE2 after rainfall events (for model calibration - Section 3.1). Results of an inspection of the condition of all ponds and drainage structures. Results of an inspection of the condition of all ponds and drainage structures. Results of an inspection of the condition of all ponds and drainage structures. Inspection of ponds and drainage structures for environmental purposes occur regularly, particularly after rain, However, if no actions are required, records are not kept of each of these inspections. Daily inspections are undertaken by the Site Supervisor which assess these structures and dams from a safety perspective. If any of these structures are observed to require maintenance, this is raised following each inspection, with action taken. Results of an inspection of the condition of any rehabilitated areas. Results of an inspection of the condition of any required, though it is observed on a regular basis by the Site Supervisor and Quarry Manager. All other areas which will require rehabilitation are still in use, and as such no rehabilitation has been undertaken. Identification of any areas of disturbed soil that As above, no other areas of disturbed soil are		as required by the EPA.
rainfall data. Results of an inspection of the volumes of water collected in Dam 8 and RE2 after rainfall events (for model calibration - Section 3.1). Results of an inspection of the condition of all ponds and drainage structures. Results of an inspection of the condition of all ponds and drainage structures. Inspection of ponds and drainage structures for environmental purposes occur regularly, particularly after rain, However, if no actions are required, records are not kept of each of these inspections. Daily inspections are undertaken by the Site Supervisor which assess these structures and dams from a safety perspective. If any of these structures are observed to require maintenance, this is raised following each inspection, with action taken. Results of an inspection of the condition of any rehabilitated areas. Only one location has been rehabilitated, which is a bund constructed along the southern boundary of the Site. This bund is fully re-vegetated, and no formal inspections are required, though it is observed on a regular basis by the Site Supervisor and Quarry Manager. All other areas which will require rehabilitation are still in use, and as such no rehabilitation has been undertaken. Identification of any areas of disturbed soil that	Results of an inspection of the untreated	N/A, this kind of discharge mentioned in the
Results of an inspection of the volumes of water collected in Dam 8 and RE2 after rainfall events (for model calibration – Section 3.1). Results of an inspection of the condition of all ponds and drainage structures. Results of an inspection of the condition of all ponds and drainage structures. Inspection of ponds and drainage structures for environmental purposes occur regularly, particularly after rain, However, if no actions are required, records are not kept of each of these inspections. Daily inspections are undertaken by the Site Supervisor which assess these structures and dams from a safety perspective. If any of these structures are observed to require maintenance, this is raised following each inspection, with action taken. Results of an inspection of the condition of any rehabilitated areas. Only one location has been rehabilitated, which is a bund constructed along the southern boundary of the Site. This bund is fully re-vegetated, and no formal inspections are required, though it is observed on a regular basis by the Site Supervisor and Quarry Manager. All other areas which will require rehabilitation are still in use, and as such no rehabilitation has been undertaken. Identification of any areas of disturbed soil that As above, no other areas of disturbed soil are	discharge records, and comparison with	WMP did not occur during the reporting
water collected in Dam 8 and RE2 after rainfall events (for model calibration - Section 3.1). Results of an inspection of the condition of all ponds and drainage structures. Inspection of ponds and drainage structures for environmental purposes occur regularly, particularly after rain, However, if no actions are required, records are not kept of each of these inspections. Daily inspections are undertaken by the Site Supervisor which assess these structures and dams from a safety perspective. If any of these structures are observed to require maintenance, this is raised following each inspection, with action taken. Results of an inspection of the condition of any rehabilitated areas. Only one location has been rehabilitated, which is a bund constructed along the southern boundary of the Site. This bund is fully re-vegetated, and no formal inspections are required, though it is observed on a regular basis by the Site Supervisor and Quarry Manager. All other areas which will require rehabilitation are still in use, and as such no rehabilitation has been undertaken. Identification of any areas of disturbed soil that As above, no other areas of disturbed soil are		period.
events (for model calibration - Section 3.1). Results of an inspection of the condition of all ponds and drainage structures. Inspection of ponds and drainage structures for environmental purposes occur regularly, particularly after rain, However, if no actions are required, records are not kept of each of these inspections. Daily inspections are undertaken by the Site Supervisor which assess these structures and dams from a safety perspective. If any of these structures are observed to require maintenance, this is raised following each inspection, with action taken. Results of an inspection of the condition of any rehabilitated areas. Only one location has been rehabilitated, which is a bund constructed along the southern boundary of the Site. This bund is fully re-vegetated, and no formal inspections are required, though it is observed on a regular basis by the Site Supervisor and Quarry Manager. All other areas which will require rehabilitation are still in use, and as such no rehabilitation has been undertaken. Identification of any areas of disturbed soil that As above, no other areas of disturbed soil are	Results of an inspection of the volumes of	N/A, the WMP states that subject to rainfall,
Results of an inspection of the condition of all ponds and drainage structures. Inspection of ponds and drainage structures for environmental purposes occur regularly, particularly after rain, However, if no actions are required, records are not kept of each of these inspections. Daily inspections are undertaken by the Site Supervisor which assess these structures and dams from a safety perspective. If any of these structures are observed to require maintenance, this is raised following each inspection, with action taken. Results of an inspection of the condition of any rehabilitated areas. Only one location has been rehabilitated, which is a bund constructed along the southern boundary of the Site. This bund is fully re-vegetated, and no formal inspections are required, though it is observed on a regular basis by the Site Supervisor and Quarry Manager. All other areas which will require rehabilitation are still in use, and as such no rehabilitation has been undertaken. Identification of any areas of disturbed soil that As above, no other areas of disturbed soil are		'
for environmental purposes occur regularly, particularly after rain, However, if no actions are required, records are not kept of each of these inspections. Daily inspections are undertaken by the Site Supervisor which assess these structures and dams from a safety perspective. If any of these structures are observed to require maintenance, this is raised following each inspection, with action taken. Results of an inspection of the condition of any rehabilitated areas. Only one location has been rehabilitated, which is a bund constructed along the southern boundary of the Site. This bund is fully re-vegetated, and no formal inspections are required, though it is observed on a regular basis by the Site Supervisor and Quarry Manager. All other areas which will require rehabilitation are still in use, and as such no rehabilitation has been undertaken. Identification of any areas of disturbed soil that As above, no other areas of disturbed soil are		
particularly after rain, However, if no actions are required, records are not kept of each of these inspections. Daily inspections are undertaken by the Site Supervisor which assess these structures and dams from a safety perspective. If any of these structures are observed to require maintenance, this is raised following each inspection, with action taken. Results of an inspection of the condition of any rehabilitated areas. Only one location has been rehabilitated, which is a bund constructed along the southern boundary of the Site. This bund is fully re-vegetated, and no formal inspections are required, though it is observed on a regular basis by the Site Supervisor and Quarry Manager. All other areas which will require rehabilitation are still in use, and as such no rehabilitation has been undertaken. Identification of any areas of disturbed soil that As above, no other areas of disturbed soil are		
are required, records are not kept of each of these inspections. Daily inspections are undertaken by the Site Supervisor which assess these structures and dams from a safety perspective. If any of these structures are observed to require maintenance, this is raised following each inspection, with action taken. Results of an inspection of the condition of any rehabilitated areas. Only one location has been rehabilitated, which is a bund constructed along the southern boundary of the Site. This bund is fully re-vegetated, and no formal inspections are required, though it is observed on a regular basis by the Site Supervisor and Quarry Manager. All other areas which will require rehabilitation are still in use, and as such no rehabilitation has been undertaken. Identification of any areas of disturbed soil that As above, no other areas of disturbed soil are	ponds and drainage structures.	
these inspections. Daily inspections are undertaken by the Site Supervisor which assess these structures and dams from a safety perspective. If any of these structures are observed to require maintenance, this is raised following each inspection, with action taken. Only one location has been rehabilitated, which is a bund constructed along the southern boundary of the Site. This bund is fully re-vegetated, and no formal inspections are required, though it is observed on a regular basis by the Site Supervisor and Quarry Manager. All other areas which will require rehabilitation are still in use, and as such no rehabilitation has been undertaken. Identification of any areas of disturbed soil that		
Daily inspections are undertaken by the Site Supervisor which assess these structures and dams from a safety perspective. If any of these structures are observed to require maintenance, this is raised following each inspection, with action taken. Only one location has been rehabilitated, which is a bund constructed along the southern boundary of the Site. This bund is fully re-vegetated, and no formal inspections are required, though it is observed on a regular basis by the Site Supervisor and Quarry Manager. All other areas which will require rehabilitation are still in use, and as such no rehabilitation has been undertaken. Identification of any areas of disturbed soil that As above, no other areas of disturbed soil are		
Supervisor which assess these structures and dams from a safety perspective. If any of these structures are observed to require maintenance, this is raised following each inspection, with action taken. Results of an inspection of the condition of any rehabilitated areas. Only one location has been rehabilitated, which is a bund constructed along the southern boundary of the Site. This bund is fully re-vegetated, and no formal inspections are required, though it is observed on a regular basis by the Site Supervisor and Quarry Manager. All other areas which will require rehabilitation are still in use, and as such no rehabilitation has been undertaken. Identification of any areas of disturbed soil that		
dams from a safety perspective. If any of these structures are observed to require maintenance, this is raised following each inspection, with action taken. Results of an inspection of the condition of any rehabilitated areas. Only one location has been rehabilitated, which is a bund constructed along the southern boundary of the Site. This bund is fully re-vegetated, and no formal inspections are required, though it is observed on a regular basis by the Site Supervisor and Quarry Manager. All other areas which will require rehabilitation are still in use, and as such no rehabilitation has been undertaken. Identification of any areas of disturbed soil that		
structures are observed to require maintenance, this is raised following each inspection, with action taken. Results of an inspection of the condition of any rehabilitated areas. Only one location has been rehabilitated, which is a bund constructed along the southern boundary of the Site. This bund is fully re-vegetated, and no formal inspections are required, though it is observed on a regular basis by the Site Supervisor and Quarry Manager. All other areas which will require rehabilitation are still in use, and as such no rehabilitation has been undertaken. Identification of any areas of disturbed soil that As above, no other areas of disturbed soil are		
maintenance, this is raised following each inspection, with action taken. Results of an inspection of the condition of any rehabilitated areas. Only one location has been rehabilitated, which is a bund constructed along the southern boundary of the Site. This bund is fully re-vegetated, and no formal inspections are required, though it is observed on a regular basis by the Site Supervisor and Quarry Manager. All other areas which will require rehabilitation are still in use, and as such no rehabilitation has been undertaken. Identification of any areas of disturbed soil that Manager. As above, no other areas of disturbed soil are		- · · · · ·
Results of an inspection of the condition of any rehabilitated areas. Only one location has been rehabilitated, which is a bund constructed along the southern boundary of the Site. This bund is fully re-vegetated, and no formal inspections are required, though it is observed on a regular basis by the Site Supervisor and Quarry Manager. All other areas which will require rehabilitation are still in use, and as such no rehabilitation has been undertaken. Identification of any areas of disturbed soil that Identification of any areas of disturbed soil are		· ·
Results of an inspection of the condition of any rehabilitated areas. Only one location has been rehabilitated, which is a bund constructed along the southern boundary of the Site. This bund is fully re-vegetated, and no formal inspections are required, though it is observed on a regular basis by the Site Supervisor and Quarry Manager. All other areas which will require rehabilitation are still in use, and as such no rehabilitation has been undertaken. Identification of any areas of disturbed soil that Only one location has been rehabilitated, which is a bund constructed along the southern boundary of the Site. This bund is fully re-vegetated, and no formal inspections are required, though it is observed on a regular basis by the Site Supervisor and Quarry Manager. All other areas which will require rehabilitation are still in use, and as such no rehabilitation has been undertaken.		
rehabilitated areas. which is a bund constructed along the southern boundary of the Site. This bund is fully re-vegetated, and no formal inspections are required, though it is observed on a regular basis by the Site Supervisor and Quarry Manager. All other areas which will require rehabilitation are still in use, and as such no rehabilitation has been undertaken. Identification of any areas of disturbed soil that Which is a bund constructed along the souther areas along the southern boundary of the Site. This bund is fully re-vegetated, and no formal inspections are required, though it is observed on a regular basis by the Site Supervisor and Quarry Manager. All other areas which will require rehabilitation has been undertaken. Identification of any areas of disturbed soil that	Popults of an inspection of the condition of any	
southern boundary of the Site. This bund is fully re-vegetated, and no formal inspections are required, though it is observed on a regular basis by the Site Supervisor and Quarry Manager. All other areas which will require rehabilitation are still in use, and as such no rehabilitation has been undertaken. Identification of any areas of disturbed soil that As above, no other areas of disturbed soil are		-
fully re-vegetated, and no formal inspections are required, though it is observed on a regular basis by the Site Supervisor and Quarry Manager. All other areas which will require rehabilitation are still in use, and as such no rehabilitation has been undertaken. Identification of any areas of disturbed soil that As above, no other areas of disturbed soil are	renabilitateu areas.	
are required, though it is observed on a regular basis by the Site Supervisor and Quarry Manager. All other areas which will require rehabilitation are still in use, and as such no rehabilitation has been undertaken. Identification of any areas of disturbed soil that As above, no other areas of disturbed soil are		_
regular basis by the Site Supervisor and Quarry Manager. All other areas which will require rehabilitation are still in use, and as such no rehabilitation has been undertaken. Identification of any areas of disturbed soil that As above, no other areas of disturbed soil are		
Manager. All other areas which will require rehabilitation are still in use, and as such no rehabilitation has been undertaken. Identification of any areas of disturbed soil that As above, no other areas of disturbed soil are		
All other areas which will require rehabilitation are still in use, and as such no rehabilitation has been undertaken. Identification of any areas of disturbed soil that As above, no other areas of disturbed soil are		, ,
are still in use, and as such no rehabilitation has been undertaken. Identification of any areas of disturbed soil that As above, no other areas of disturbed soil are		_
has been undertaken. Identification of any areas of disturbed soil that As above, no other areas of disturbed soil are		· ·
Identification of any areas of disturbed soil that As above, no other areas of disturbed soil are		
	Identification of any areas of disturbed soil that	

	levels have not yet been reached, or the areas are presently in use for stockpile storage.
Results of an inspection of the water quality monitoring results.	Water quality monitoring results are reviewed upon receipt, and compared to the limits and requirements presented in the WMP. The data is included in the monthly Environmental Monitoring Reports which are uploaded to the Multiquip website, as well as the Annual Review.
Results of an inspection of the condition of the receiving water (Section 4.2).	These observations were included in the discharge reports prepared during the reporting period, as per Section 5.5.5.
Provide recommendations to the site manager for any remedial actions necessary to ensure compliance with the operational license.	This is done on an ad-hoc basis, or via regular compliance meetings between 4Pillars and the Quarry Manager, with discussion points and recommendations circulated following each meeting.
Provide a clear statement as to whether the conditions of the operational license are being met. If they are not he/she will report on any breaches of the operation license and liaise with DPI Water to recommend any remedial actions necessary.	This is done on an ad-hoc basis, or via regular compliance meetings with the Quarry Manager, with discussion points and recommendations circulated following each meeting. Recommendations regarding notification of identified non-compliances are also discussed during these meetings.
Report on any unforeseen impacts and liaise with DPI Water to recommend any remedial actions necessary.	N/A during the reporting period.

6.2.7 Surface Water Response Plan

The Surface Water Response Plan presented in Table 3 of the WMP has been reproduced in Table 33, below, along with the status of each trigger during the reporting period. No triggers were observed during the reporting period that required actions to be implemented.

Table 33: Surface Water Response Plan presented in Table 3 of the WMP, and status during the reporting period.

Trigger	Status during reporting period
Discharge from CP1, CP2 or CP3 when	No Action Required - no discharge from CP1,
combined rainfall has been less than 41mm in	CP2, or CP3 during the reporting period.
the previous five days.	
Unable to treat water to less than 50mg/L	No Action Required - no discharge from CP1,
before discharge.	CP2, or CP3 during the reporting period. All
	discharge was from the Old Pit, and in
	accordance with EPL-approved discharge trial
	and extension.
Water quality measurements exceed triggers	N/A - only relevant if at any time the settling
described in Section 4.1.	volume of Dam CP3 is compromised, and off-
	site disposal is required. This did not occur
	during the reporting period.
Significant changes to the watercourse	No Action Required - no significant changes
downstream of CP3 (Section 4.2).	observed.
Signs of pollutants downstream of CP3 (e.g.	No Action Required - no pollutants observed.
foams, oil and scum).	

Signs of wastewater effluent at soil surface.	No Action Required - no signs of wastewater effluent observed.
Re-use from ponds less than predicted, over- reliance on bore water.	No Action Required - accumulated site water was utilised for site activities (e.g. dust suppression) where possible, over bore water. Only 18.6% of the entitlement from WAL 30111 at BHAP6 was used during the reporting period.
Re-vegetation not occurring in required time frame.	It is assumed that "re-vegetation" here refers to within the watercourse south of the Approved Extraction Area, as the only other reference to vegetation within the WMP refers to this location, in Section 4.2. No impacts to vegetation were observed during the reporting period, and as such no re-vegetation was required.
Any unforeseen impact.	No Action Required- no unforeseen impacts arose that required further assessment.

7. Rehabilitation

No rehabilitation work was undertaken on previously disturbed land during the reporting period. Limited backfilling in the west of the "Old Pit" in the south-west of the Approved Extraction Area was undertaken, made possible by the further discharge associated with the short-term continuation of the discharge trial. Backfilling of the "White Pit" in the south-east of the Approved Extraction Area with overburden was undertaken during 2024, with some areas close to attaining final landform. This will be continued in the next reporting period, alongside extractive activities.

All rehabilitation work proposed in the 24 December 2021 notification of non-compliances is pending, awaiting direction from the Department.

On 20 March 2025 - during the preparation of this Annual Review - correspondence from DPHI was received confirming that the process of reviewing, revising and resubmitting management plans for assessment and approval may recommence. In accordance with this update, the review and submission of the Landscape Management Plan is to be carried out in the next reporting period (i.e. 2025). Further direction regarding rehabilitation will be available once this plan is finalised.

The MQA2 stockpile material was not moved during the reporting period, and as such rehabilitation in this area was not commenced.

8. Community

8.1 Community meetings

One Community Consultative Committee (**CCC**) meeting was held by Multiquip in 2024 (May), as a forum for the provision of environmental monitoring data and to facilitate discussions relating to environmental performance. The minutes of CCC meetings are made available via the company website. Key concerns and questions brought up by residents and members of the CCC during 2024 related particularly to road works, the condition of the haul routes and the Council's involvement, as well as more generally

regarding water management, noise, and rehabilitation activities. Where possible, Multiquip acts on the concerns raised, or otherwise provides comments and clarification.

A second CCC meeting was intended to be held in November 2024, however the Independent Chairperson indicated their intention to resign from the role during the May meeting. A suitable replacement was not engaged prior to the proposed meeting, and it was accordingly rescheduled. Multiquip has been communicating with DPHI around this issue, and intend to engage a new Independent Chairperson in early 2025, with Multiquip currently in discussions with a potential replacement, in order to recommence the CCC meetings.

8.2 Complaints

Three complaints were received by Multiquip during 2024, relating to noise, as shown in Table 34. All complaints during 2024 were received in the afternoon, on Mondays. Where appropriate, complaints are followed-up, and corrective actions taken when required. The number of complaints has decreased and is currently steady, as per the following: 2023 (three complaints), 2022 (three complaints), 2021 (six complaints), 2020 (11 complaints), 2019 (16 complaints).

Complaints are recorded in an electronic register, with details of the complainant, date, time, method of delivery, the Multiquip contact who received the complaint, the subject of the complaint, information on corrective actions and additional comments noted. A summarised complaints report - i.e. with identifying information of the complainants removed - is updated as required and published to Multiquip's website.

We understand that regulators (including the NSW EPA) may on occasion receive direct correspondence or complaints from community members regarding the quarry. Multiquip remains in liaison with regulators regarding these issues, and open to rectifying any concerns raised. In 2024, no community complaints were formally passed on to Multiquip from regulators.

Notwithstanding complaints received, monitoring undertaken demonstrates compliance with the project's performance criteria for noise.

Multiquip continues to operate a phone complaints line, however most complaints are made directly through site management personnel, due to their familiarity with complainants.

Table 34: Complaints received during 2024.

Date	Time (approx.)	Topic	Description
26/02/2024	5:00 PM	Noise	Alleged site noise audible at residence.
4/03/2024	2:30 PM	Noise	Alleged 60 dB noise levels at residence.
12/08/2024	12:00 PM	Noise	Alleged site noise audible at residence.

9. Independent Environmental Audit

Schedule 5 Condition 6 of the Project Approval requires that an Independent Environmental Audit (IEA) is conducted every 3 years. An IEA was conducted in 2022 by Ramboll Australia Pty Ltd and as such no IEA was required during the reporting period. The preceding IEA was published by Groundwork Plus in January 2019, covering the period of November 2015 to November 2018. The next IEA is scheduled for early 2025.

The 2022 IEA contained a number of recommendations regarding non-compliances with the Project Approval and opportunities for improvement with conditions of both the Project Approval and EPL. The current status of these recommendations has been presented in Table 35 and Table 36, below.

Table 35: Response to recommendations raised in the IEA - Non-compliances (Project Approval 07_0155).

NC#	Condition ID	Audit Recommendation	Response	Status - 2023 Annual Review	Status - 2024 Annual Review
NC1	Schedule 2 Condition 2	Agree resolution of non-compliances with approved project layout with the Department, which may involve a further modification of the Project Approval.	Awaiting outcome and further direction from DPE on this issue.	No change - awaiting outcome and further direction from the Department.	No change.
NC2	Schedule 2 Condition 13	Finalise resolution of roads issues with Council to enable finalisation of VPA.	Discussions to be continued and finalised when possible.	No change - discussions are ongoing.	Progressing, with some positive movement and a meeting in late 2024.
NC3	Schedule 3 Condition 1	Confirm that the Planning Secretary has been provided with a survey plan of the extraction area boundaries and their GPS coordinates or, if not, provide the survey plan to the Planning Secretary.	The Department (Michael Wood) was contacted via email on 14 October 2022 with a copy of the survey plan to confirm whether they had evidence of prior receipt. A response was received on 17 October 2022, stating that the documents had been received via the Major Projects Portal as part of submission PA-5, presumably in January or	Completed, no further action required.	No change.

NC#	Condition ID	Audit Recommendation	Response	Status - 2023 Annual Review	Status - 2024 Annual Review
			February 2021. Follow-up questions sent by the Department on 8 February 2021 were not replied to at the time, but were replied to via email on 18 October 2022.		
NC4	Schedule 3 Condition 1A	Ensure boundaries of the approved areas of extraction are clearly marked in a manner that allows them to be easily identified.	Boundary on site to be clearly re-marked with stakes/bunting.	Boundaries were marked with stakes, and bund walls have since been constructed over these stakes to provide a physical delineation of the area on Site. Site staff are aware of these boundaries.	No change.
NC5	Schedule 3 Condition 11	No recommendation is made as the non-compliance has been rectified.	No action required - penalty notice and works approval for WAL issued.	Completed, no further action required.	No change.
NC6	Schedule 3 Condition 24	No recommendation is made as the revised AHMP was submitted to DPE for approval.	No action required - awaiting response from DPE.	No update - the Department is not currently assessing and approving any revised plans. The revised AHMP submitted was withdrawn at DPHI's request in August 2024.	No change, however management plans to be resubmitted for review and approval based on DPHI correspondence received in March 2025.

NC#	Condition ID	Audit Recommendation	Response	Status - 2023 Annual Review	Status - 2024 Annual Review
NC7	Schedule 3 Condition 27	No recommendation is made in relation to this non- compliance	No action required - refer to NC8.	No action required.	No change.
NC8	Schedule 3 Condition 29	Publish summaries of truck movement records on the quarry website and include in the Annual Review.	A process for regularly reviewing weighbridge data has been developed, and truck movement summaries prepared. A truck movement summary report for 2022 was completed and uploaded to the website on 21/10/2022. Truck movement summaries will continue to be updated and published monthly as required by Schedule 3 Condition 29, as well as being included in the Annual Review for 2022.	Completed - truck movement summaries are prepared and uploaded monthly, and included in the Annual Review.	No change, this action has continued through the reporting period.
NC9	Schedule 3 Condition 34A	Complete vegetation of the eastern visual bund wall.	Vegetation to be completed, pending outcome and further direction from DPE on the issues raised in NC1.	No further progress.	No change.
NC10	Schedule 3 Condition 41	Ensure annual production data is provided to the MEG using the standard form for that purpose.	Submissions to be reviewed to confirm that annual production data was provided to the MEG as required. This will be completed if not the case.	Production data is submitted as required.	No change.

NC#	Condition	Audit	Response	Status -	Status - 2024
	ID	Recommendation		2023 Annual Review	Annual Review
NC11	Schedule 5 Condition 5	The auditors make no recommendation as the issue was noted as a noncompliance at the time and was not repeated in the following year.	No action required - future Annual Reviews to be submitted punctually.	Completed - Annual Reviews have been submitted punctually since the Audit.	No change.
NC12	Schedule 5 Condition 5A	A process or procedure should be put in place to ensure that strategies, plans, and programs are reviewed and, if revised, submitted to the Department for approval within 3 months of an event described in parts (a) - (d) of this condition.	A management plan review procedure and associated register was prepared in response to this non-compliance. The occurrence of an event listed in Schedule 5 Condition 5A (a)-(d), is considered a 'trigger' for review, which is entered into the register. The strategies, plans, and programs will then be reviewed and revised as appropriate, with changes and dates recorded in the register. Revised documents will be submitted to the Department for approval, and the status of current documents is to be recorded in the register.	No update - while the management plan review procedure and associated register were prepared in response to this non-compliance, the Department is not currently assessing and approving any revised plans.	No change, however management plans to be resubmitted for review and approval based on DPHI correspondence received in March 2025.
NC13	Schedule 5 Condition 6	Commence process to appoint independent auditors well	No immediate action required - this has been	No update - not required at this time.	Appointment of Audit Team is underway -

NC#	Condition ID	Audit Recommendation	Response	Status - 2023 Annual Review	Status - 2024 Annual Review
		enough in advance to allow for potential delays in the approval and appointment of auditors.	noted for future reference.		audit proposed for April 2025.
NC14	Schedule 5 Condition 8	Review the sum of the Rehabilitation Bond within 3 months of the date of this Audit Report.	The Rehabilitation Bond will be reviewed within 3 months of the date of the Audit Report (i.e. by 14 January 2023).	Completed, but overdue - The draft Rehabilitation Bond Report and associated Rehabilitation Cost Estimation prepared by Eltirus Pty Ltd was submitted to DPE on 31 March 2023. A noncompliance with this requirement was raised.	No change.

Table 36: Response to recommendations raised in the IEA - Opportunities for improvement (Project Approval 07_0155 and EPL 13213).

Condition ID	Audit Recommendation	Response - 25/10/2022	Status - 2023 Annual Review	Status - 2024 Annual Review
Schedule 3 Condition 7	Establish a process to ensure environmental monitoring results reports are checked prior to be being published on the website	The offending report was reviewed and the minor discrepancies identified, determined to be due to transcription errors. All dust data was audited and corrected, with the revised report submitted for upload to the website on 18/10/2022. Data is checked when obtained from the laboratory and again when	All data is cross- checked prior to upload. No issues have been identified since the Audit.	No change.

Condition ID	Audit Recommendation	Response - 25/10/2022	Status - 2023 Annual Review	Status - 2024 Annual Review
		transcribed into summary reports for website publication. All staff involved in data management were informed of the issue and reminded of the importance of presenting accurate data.		
Schedule 3 Condition 8 EPL Condition O3.1	Review use of water sprays on rock crushing plant to optimise dust suppression.	Site staff were reminded about the importance of dust mitigation, and use of water sprays is ongoing.	Use of water sprays is ongoing as required. A Dust Management Capacity Assessment (DMCA) report was prepared and submitted to the EPA in accordance with Condition U3 of EPL 13213, (varied on 27/09/2023), with the aim of assessing air emissions from the site and making recommendations to reduce them. Implementation of recommendations from the DMCA and discussions with the EPA are	The EPL was varied on 22/11/2024 to include conditions related to the implementation of findings from the DMCA. These are underway.
Schedule 3 Condition 13 EPL Condition O4.1	Ensure that annual audits as required under Section 6 of the current Water Management Plan are undertaken, prioritise submission of the revised Water Management Plan to the Department for approval and ensure a variation of the EPL is made to reflect the new Water Management Plan, when approved.	Noted. The discrepancy between the current 2017 Water Management Plan and the reference to a 2010 Water Management Plan within EPL Condition O4.1 was identified and raised as a noncompliance in the 2021-22 Annual Return, submitted to the EPA on 17 October 2022. Following	ongoing. No update - the Department is not currently assessing and approving the revised WMP. As this was expected to be a quick process, the variation of the EPL to reflect the current (but outdated) 2017 WMP was not considered a priority. An Annual Audit required by Section 6 of the	Management plans to be resubmitted for review and approval based on DPHI correspondence received in March 2025. Reporting equivalent to the annual audit required by Section 6 was carried out and provided as required.

Condition	Audit	Response -	Status - 2023	Status - 2024
ID	Recommendation	25/10/2022	Annual Review	Annual Review
Schedule 3 Condition 17 EPL Condition P1.3	Consult with the EPA on decommissioning of BHAP1 and BHAP5 and any necessary variation of the licence. Ensure the revised Groundwater Monitoring Program reflects changes to monitoring bores and reflects consultation with the EPA and the Department on decommissioning of BHAP1 and BHAP5	completion and approval of the revised Water Management Plan, a variation to the EPL will be lodged to revise the reference in Condition O4.1. The NRAR Direction was varied on 8 September 2022 to allow rehabilitation of BHAP1 and BHAP5 as an alternative to decommissioning (Specified measure 1). The EPA and DPE were consulted about the proposed works on 7 October 2022, and a response was received from the EPA on 14 October 2022. Following the works, the revised Groundwater Monitoring Program will reflect any changes to monitoring bores,	Annual Review 2017 WMP was not carried out in the reporting period. The set of data will be provided promptly, and on an ongoing basis as required. Completed, no further action required. The works did not impact the implementation of monitoring as required by the 2017 WMP.	No change.
		and the EPL will be updated if required.	N. I.	
Schedule 5 Condition 5B	Ensure that revised management plans include: • a protocol for managing and reporting any incidents; complaints; non-compliances with statutory requirements; and exceedances of the impact assessment	Noted. Revised management plans will include the suggested contents.	No update - the Department is not currently assessing and approving any revised plans.	Management plans to be resubmitted for review and approval based on DPHI correspondence received in March 2025.

Condition ID	Audit Recommendation	Response - 25/10/2022	Status - 2023 Annual Review	Status - 2024 Annual Review
	criteria and/or performance criteria; and a protocol for periodic review of	23/10/2022	Annual Review	Annual Review
Schedule 5 Condition 10	the plan. Review the quarry website to ensure all required information is publicly available.	The quarry website is reviewed monthly following receipt of data and preparation of documents. Any missing documentation will be uploaded. The CCC minutes for the March 2022 meeting were not finalised prior to the completion of the IEA, and due to some issues requiring revision, are expected to be finalised at the next CCC meeting scheduled for 11 November 2022. Following this, the final minutes will be published on the website as required.	Ongoing as required. All information and documents are uploaded as required.	No change.
EPL Condition A1.1	Consider whether a variation of the EPL is required to increase the scale of the activity in line with the modification of the project approval.	Noted. Current operations do not exceed 400,000 tpa, which is within the allowances of the EPL (>100000 - 500000 t annually). When operations are expected to increase >500,000 t, a variation to the EPL will be lodged.	No change - operations remain within EPL limits.	No change.
EPL Condition L4.1	Ensure a variation of this condition is made prior to product transportation commencing before 7am as permitted under MP07_0155.	Noted. As above, a variation to the EPL will be lodged at the appropriate time.	No change.	No change.

Condition ID	Audit	Response -	Status - 2023	Status - 2024
	Recommendation	25/10/2022	Annual Review	Annual Review
EPL Condition R1.1	Implement a crosscheck to ensure all reporting of complaints aligns.	Staff involved in complaints management were informed of the issue and continue to perform regular confirmation of complaints when summarised for website upload.	Ongoing - complaints documents are cross-checked during preparation.	No change.

10. Incidents and non-compliances

10.1 Incidents in 2024 reporting period

There were no environmental incidents at the quarry during the 2024 reporting year.

Elevated primary dust levels above the limit values prescribed in the Project Approval were observed on two occasions. Assessment of these results - including wind and other monitoring locations - concluded that the levels were not attributed to quarrying activities, and as such, the limits were not considered to have been exceeded. Details are provided in Section 5.3.

10.2 Non-compliances in 2024 reporting period

Non-compliance with two conditional requirements of PA 07_0155 (Mod 3) were identified, being Schedule 3 Condition 4 and Schedule 3 Condition 27. This does not include any non-compliances that are ongoing and were reported in the previous Annual Review.

Schedule 3 Condition 4

Overview

Schedule 3 Condition 4 details operating hours for quarry operations, including transport. As detailed in Section 3.5, it was identified that there were eight weekdays where truck movements occurred after 6 pm, and five Saturdays where truck movements occurred after 1 pm, which are outside of the permitted operating hours, a total of 14 days. This was a total of 28 movements (0.24% of total truck movements for 2024), an average of two movements (i.e. a single truck entering and exiting) per day of non-compliance.

Causes and consequences

Based on a review of the data, investigations, and interviews with key personnel, the cause of the non-compliances was attributed largely due to reliance on inadequate manual systems.

CEAL Limited trading as Multiquip Quarries was issued with a Show Cause Notice on 22 November 2024 regarding the non-compliant truck movements in 2023 notified in a 21 October 2024 letter from 4Pillars on behalf of Multiquip, as well as the 2023 Annual Review (version 2, submitted on 14 October 2024). On 5 February 2025, DPHI issued

CEAL Limited with a Penalty Notice (\$15,000) for the 2023 non-compliances, and noted that 2024 non-compliances would be investigated following the submission and review of the 2024 Annual Review.

Environmental impacts

The non-compliances were considered to present negligible or no potential for environmental harm, especially considering the high percentage of compliant movements as compared to the relative infrequency and low number of non-compliant movements. No complaints were received regarding truck movements outside of permitted operating hours. No product loading and dispatch was undertaken on Sundays or public holidays.

Proposed actions

These non-compliances were notified to DPHI in a 11 December 2024 response to the Show Cause notice, along with the actions detailed in Section 3.5, which have been reproduced in Table 37, below, along with their current status.

Table 37: Improvements presented in the 11 December 2024 response to the Show Cause and current status.

Proposed improvement	Status as of 2024 Annual Review
Obtaining a new weighbridge system from	Underway
GTick.	Order has been placed with GTick, lead-
	time approx. 8 weeks. Expected
	installation mid-May.
Training of allocators and other key	Completed
personnel about compliance with consent	Toolbox talk was conducted on 10
conditions relating to truck movements.	December 2024.
Performing daily reviews of weighbridge	Ongoing
data to assess any actual, or near, non-	This is conducted daily.
compliances that day. If so, implementation	
of training and disciplinary action as	
necessary.	
Resolving outstanding requirements of the	Underway
consent, to permit earlier weighbridge	This is contingent on the approval of
operations and alleviate pressure on the	management plans and other items, as
7am to 8am time period particularly, as well	discussed elsewhere in this Annual
as generally throughout the day.	Review.
Consideration of an amendment to consent	Not yet considered
conditions, to make compliance more	This is a potential future action. Not
straightforward.	considered a priority at this time.

Schedule 3 Condition 27

Overview

Schedule 3 Condition 27 details hourly limits for truck movements at the site (either arrival or dispatch). As detailed in Section 3.5, it was identified that there were 80 movements in 2024 (0.70% of total movements) which were in excess of these permitted hourly limits.

These movements occurred across 46 days. Of these, the vast majority (93%) were found to have occurred in the 7-8 am period.

Causes and consequences

As above, the cause of the non-compliances was attributed largely due to reliance on inadequate manual systems.

Environmental impacts

The non-compliances were considered to present negligible or no potential for environmental harm, especially considering the high percentage of compliant movements as compared to the relative infrequency and low number of non-compliant movements. No complaints were received regarding truck movements in excess of hourly limits.

Proposed actions

76 of the non-compliant movements were notified to DPHI in a 11 December 2024 response to the Show Cause notice. Four movements occurred in December 2024 that were in excess of the permitted hourly limits, which were not known at the time of the preparation of the response.

These four movements will be notified separately as non-compliances.

Actions to be taken to ensure ongoing compliance are as mentioned above and in Table 37.

10.3 Non-compliances identified in 2023 Annual Review

Updates to the non-compliances identified in 2023 Annual Review that arose during the reporting period are discussed below.

Non-compliance with four conditional requirements of PA 07_0155 (Mod 3) were identified, being Schedule 2 Condition 13, Schedule 5 Condition 4, Schedule 5 Condition 8, and Schedule 3 Conditions 4 and 27.

Schedule 2 Condition 13

Multiquip has continued to engage proactively with Council to attempt to resolve the outstanding Voluntary Planning Agreement (VPA), including attending a meeting in early December 2024. DPHI has been kept updated throughout the reporting period.

Schedule 5 Condition 4

Regular meetings between Multiquip management and engaged external environmental consultants have been held, as noted in the 2023 Annual Review for this non-compliance.

Schedule 5 Condition 8

No further actions were proposed in the 2023 Annual Review for this non-compliance.

Schedule 3 Condition 4

The actions proposed in the 2023 Annual Review for this non-compliance were undertaken, including:

- Notification of non-compliance to DPHI.
- Operating hours reiterated to site staff.

• Monthly reviews of weighbridge records including an assessment of compliance to ensure that any identified non-compliances can be acted upon promptly.

Furthermore, a review of alternative weighbridge software systems was undertaken. GTick Systems have been selected and planned installation is scheduled for mid-May 2025.

On 5 February 2025, DPHI issued CEAL Limited with a Penalty Notice (\$15,000) for the 2023 non-compliances.

10.4 Regulatory correspondence

A summary of correspondence received in relation to official cautions, warning letters etc. is provided in Table 38, below. All issues raised by various regulatory agencies are treated seriously and acted upon. Automatic replies and email correspondence related to online submissions have not been included in the table. Outgoing correspondence (i.e. on behalf of Multiquip) has not been included.

Table 38: Summary of official correspondence received during 2024.

Date	Regulatory agency	Issue	Company Response
27/05/2024	EPA	Dust management, comments and RFI - draft conditions of the revised Pollution Reduction Program placed on the EPL.	Response provided on 13/08/2024.
27/08/2024	DPHI	2023 Annual Review - additional information required.	2023 Annual Review revised and submitted along with responses to comments on 14/10/2024 following an approved deadline extension.
16/10/2024	DPHI	Blasting - response to proposed blasting notification and proposed submission of modification for the development to permit the activity.	None provided (not required).
19/10/2024	DPHI	AHMP - response to correspondence and proposed staging of assessment.	Response provided on 20/12/2024.
22/10/2024	DPHI	Show Cause - non- compliance with transport limits.	Response provided on 11/12/2024 following an approved deadline extension.

11. Activities in the next reporting period

The following activities are proposed in 2025 (Table 39).

Table 39: Activities proposed in 2025.

Proposed activity	Timeframe
Continuation of mining activities at the site. Indicatively expected to be 400,000 tpa to be increased to 580,000 tpa when	Ongoing
appropriate documentation etc. is approved.	
Further rehabilitation and landscaping of visual bunds, pending approval from DPHI.	Ongoing, pending DPHI
Monitoring	Ongoing
SWL of bores monthly	Oligonig
Deposited dust monthly	
Water sampling quarterly and annually	
Particulate matter continuously (assessed monthly)	
Noise twice annually	
Discharge sampling (characterisation and validation) as	
required, if ongoing discharge approved	
Discharge water quality sampling monthly during	
discharge, if ongoing discharge approved	
Ambient water quality sampling monthly during	
discharge, if ongoing discharge approved	
Implementation of additional dust management measures arising	Ongoing
from the DMCA, as per EPL.	
Implementation of weed control program(s).	Ongoing
	throughout year as
	appropriate
	(dependant on
	seasons)
Relocation of weather station to allow for extension of quarrying.	By end of 2025
Submission of modification to Project Approval (Modification 4) for blasting activities.	Mid-2025
Submission of modification to Project Approval (Modification 5)	TBC, pending DPHI
to ensure activities align with Approval.	
Attendance at all Community Consultative Committee (CCC) meetings.	As arising
Submission of EPL variation to remove identified bores from EPL.	Mid-2025
Close-out of Development Control Order.	TBC, pending
·	outcome of
	compliance
	investigation
Completion and lodgement of Modification 3 Environmental Management Plans.	Mid-2025
Application for ongoing discharge as a condition of the EPL.	Mid-2025
Finalise Voluntary Planning Agreement (VPA) with Goulburn	Indeterminate,
Mulwaree Council.	intending to meet
	prior to mid-2025
Installation of new weighbridge software system	May 2025

12. References

The Department of Planning and Environment. (2015). Annual Review Guideline. Sydney: NSW Government.